## BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479


FOR OFFICE USE ONLY		7
UNIQUE 972 90-40-	5873	D07
QUAD		
SERIES		
NEG. NO.		

NEW TORK STATE PARKS AND RECREATION	SERIES
ALBANY, NEW YORK (518) 474-0479	NEG. NO.
YOUR NAME: BUFFALO FRIENDS OF OLMSTED PAR	RKS DATE: July 25, 1984
P. O. BOX 590	
YOUR ADDRESS: BUFFALO, NEW YORK 14205 = 0590	TELEPHONE:
ORGANIZATION (if any):	
* * * * * * * * * * * * * * * * * * * *	* * * * * * * * * * * * * * *
IDENTIFICATION	
1. BUILDING NAME(S): 2. COUNTY: Erie TOWN/CITY: B 3. STREET LOCATION: 17 Florence All 4. OWNERSHIP: a. public b. private \boxed{\text{S}} 5. PRESENT OWNER: Wilda Levin	7
2. COUNTY: Erie TOWN/CITY:B	BuffaloVILLAGE:
3. STREET LOCATION: 17 Florence Ave	
4. OWNERSHIP: a. public □ b. private ☒	730 Parkside Ave.
5. PRESENT OWNER: Wilda Levin	ADDRESS: Buffalo, NY 14216
6. USE: Original: Residential	Present: Residential
7. ACCESSIBILITY TO PUBLIC: Exterior visible from	om public road: Yes 🖾 No 🗆
Interior accessible	e: Explain by permission
DESCRIPTION	•
	c. brick \( \square \) d. board and batten \( \square \)
MATERIAL: e. cobblestone  f. shingles	g. stucco Other:
9. STRUCTURAL a. wood frame with interlocking	g joints 🗆
SYSTEM: b. wood frame with light mem	bers 🗴
(if known) c. masonry load bearing walls	77 7
d. metal (explain)	
e. other	
0. CONDITION: a. excellent  b. good  c	
1. INTEGRITY: a. original site   ■ b. moved □	if so, when?
c. list major alterations and dates (if	known):

12. PHOTO: 37-25a



13. MAP:



14.	THREATS TO BUILDIN	G: a. none known ☑ b. zoning □ c. roads □ d. developers □ e. deterioration □
15.	RELATED OUTBUILDIN	f. other:
		d. privy  e. shed  f. greenhouse  g. shop  h. gardens
		i. landscape features: <u>tree and shrubs in front yard</u> j. other:
16.	SURROUNDINGS OF T	HE BUILDING (check more than one if necessary): a. open land □ b. woodland □
		c. scattered buildings
		d. densely built-up 🖾 e. commercial 🗆
		f. industrial  g. residential  h. other:
17.		OF BUILDING AND SURROUNDINGS:
-		ructure is in an historic district) ated on a standard sized corner lot within
O f	lmsted's Parksio rom Delaware Par	de subdivision. House is located three blocks ck, which was designed by Olmsted and is listed Register, and southeast of the Zoo.
18.	OTHER NOTABLE FEA	TURES OF BUILDING AND SITE (including interior features if known):
T	wo and a half st	cory frame with front facing gable roof. Full-
W	idth flat roof p	porch. Rough cut, regular course stone base and
р	edestals. Tapel	red square Doric supports with column elaboration. a spindle balustrade. Glass paneled door flanked
		rinder. Biret floor left have bee double hung 1/1
SIC	NIFICANCE window	v. Plain window surround. Second floor semi-
19.	DATE OF INITIAL CON	STRUCTION: c. 1901
		hung 1/1 window. Pedimented
	ARCHITECT:	gable, shingled, has paired ple-hung 1/1 windows. Entablature window head.
	BUILDER: Saw-	-tooth shingles at window sill, top and raking
	corr	nice.
		CHITECTURAL IMPORTANCE: A typical frame gabled
r	esidence found to	throughout Buffalo. Florence Avenue extends from arkside Avenue, paralleling Robie Street.
L	ocated within th	ne first section of the Parkside subdivision to
b	e developed, Flo	prence Avenue was deeded to the city by Jacob
D	avis in 1887. A	Although Olmsted's early 1870's maps of "The
		street angling from the intersection of Main Parkside Avenue, when it was finally developed
		was modified to parallel Humboldt Avenue. It
		Il followed Olmsted's rule that a subdivision
S	treet "not lead	with special directness toward the town."
21.	SOURCES: City	Tax Assessor Field Sheets
-1.	County	Census Records, 1905
		ed's Sketch Map of Buffalo, 1876 apers of Frederick Law Olmsted, Vol. III, by
22.	Char	cles E. Beveridge & David Schuyler, eds. (1983).
2.4.	IIILIIL.	and the second of the second s

Residence