## **BUILDING-STRUCTURE INVENTORY FORM**

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY		D	0
UNIQUE SITE NO.	4775		
QUAD		_	
SERIES	-	-	
NEG. NO.			

ALBANY, NEW YORK (518) 474-0479 NEG. NO
YOUR NAME: BUFFALO FRIENDS OF OLMSTED PARKS DATE: May 25, 1983 P. O. BOX 590
YOUR ADDRESS: BUFFALO, NEW YORK 14205 = 0590 TELEPHONE:
ORGANIZATION (if any):
* * * * * * * * * * * * * * * * * * * *
IDENTIFICATION
L BUILDING NAME (S):
2. COUNTY:ErieTOWN/CITY:BuffaloVILLAGE:
3. STREET LOCATION: 1334 Amherst St:
4. OWNERSHIP: a. public □ b. private ☒
5. PRESENT OWNER: Blanche Kellner ADDRESS: 1334 Amherst Street
6. USE: Original: Residential Present: Residential
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes 🗷 No 🗆
Interior accessible: Explain by permission
DESCRIPTION
8. BUILDING a. clapboard  b. stone  c. brick d. board and batten
MATERIAL: e. cobblestone  f. shingles g. stucco other: aluminum siding
9. STRUCTURAL a. wood frame with interlocking joints
SYSTEM: b. wood frame with light members 🗵
(if known) c. masonry load bearing walls
d. metal (explain)
e. other
0. CONDITION: a excellent $\square$ b. good $\boxtimes$ c. fair $\square$ d. deteriorated $\square$
1. INTEGRITY: a. original site \( \omega \) b. moved \( \omega \) if so, when?
c. list major alterations and dates (if known):

12. РНОТО: 11-34а



13. MAP:



14. THREATS TO BUILDING: a. none known   d. developers □  e. deterioration □  c. roads □  e. deterioration □
f. other:
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):  a. open land  b. woodland  c. scattered buildings  d. densely built-up  e. commercial  f. industrial  g. residential  h. other:
17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:  (Indicate if building or structure is in an historic district) Building is situated on a standard sized building lot within Olmsted's Parkside subdivision. House is directly opposite Delaware Park which was designed by F.L.O. and is listed on the National Register. A dense grove of trees and the Buffalo Zoo are across the street from this property.
18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
One and a half story frame house. Gable roof with dormer on front facade. Dormer has a curved roof and a multi-paned double door leading out to an open porch. Enclosed porch on front facade has large plate glass windows. Entrance on east side of house.
SIGNIFICANCE 19. DATE OF INITIAL CONSTRUCTION: C. 1915
ARCHITECT:
BUILDER:
20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: This section of Amherst Street, between Colvin and Parkside, was conceived by F.L.O. around 1873 as part of a residential "suburb" adjacent to Delaware Park. This suburb was called "The Parkside" by Olmsted and appears on an 1876 map drawn by him as a proposed area of curved winding streets on the north and east sides of the park. This section of Amherst Street was actually created by the City of Buffalo in 1875 when Amherst Street was extended from Delaware Avenue to Main Street. The street follows Olmsted's original plan, maintaining the picturesque character that he envisioned for the streets surrounding the park.
21. SOURCES: Buffalo City Atlas, 1894, 1915 Sandborn Map, 1916 Buffalo Index to Streets, @1896 F.L.O.'s original map for "Parkside"

22. THEME:

Frame house.