BUILDING-STRUCTURE INVENTORY FORM


DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY 029-40- UNIQUE SITE NO. 5474	DO7
QUAD	1
SERIES	
NEG. NO.	-

ALBANY, NEW YORK (518) 474-0479 NEG. NO
YOUR NAME: BUFFALO FRIENDS OF OLMSTED PARKS DATE: July 16, 1984
YOUR ADDRESS: BUFFALO, NEW YORK 14205 - 0590 TELEPHONE:
ORGANIZATION (if any):
* * * * * * * * * * * * * * * * * * * *
IDENTIFICATION
1 BUILDING NAME (S):
2 COUNTY: Erie TOWN/CITY: Buffalo VILLAGE:
3. STREET LOCATION: 32 Oakwood Pl.
1. BUILDING NAME(S): 2. COUNTY: Erie TOWN/CITY: Buffalo VILLAGE: 3. STREET LOCATION: 32 Oakwood Pi. 4. OWNERSHIP: a. public b. private 4. Ownership: a. public b. private 4. Ownership: a. public colling Appress 32 West Oakwood
5. PRESENT OWNER: RICHARD COTTINS ADDRESS: 32 West Odkwood
6. USE: Original: Residential Present: Residential
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes 🗵 No 🗆
Interior accessible: Explain by permission
DESCRIPTION
8. BUILDING a. clapboard \(\omega \) b. stone \(\omega \) c. brick \(\omega \) d. board and batten \(\omega \)
MATERIAL: e. cobblestone f. shingles g. stucco other:
9. STRUCTURAL a. wood frame with interlocking joints
SYSTEM: b. wood frame with light members \(\sigma\)
(if known) c. masonry load bearing walls
d. metal (explain)
e. other
0. CONDITION: a. excellent □ b. good ☒ c. fair □ d. deteriorated □
1. INTEGRITY: a. original site b. moved □ if so, when?
c. list major alterations and dates (if known):

12. РНОТО: 36-16а





14. THREATS TO BUI	ILDING: a. none known ⊠ b. zoning □ c. roads □ d. developers □ e. deterioration □
15. RELATED OUTBU	f. other:
	d. privy = e. shed = f. greenhouse = g. shop = h. gardens =
	i. landscape features: <u>trees and shrubs in front yard</u> j. other:
16. SURROUNDINGS	OF THE BUILDING (check more than one if necessary): a. open land □ b. woodland □
	c. scattered buildings
	d. densely built-up ⊠ e. commercial □ f. industrial □ g. residential ⊠
	h. other:
17 INTERRELATION	SHIP OF BUILDING AND SURROUNDINGS:
(Indicate if buildin	g or structure is in an historic district)
	tuated on a standard sized corner lot within side subdivision. House is located four blocks
from Delaware	Park, which was designed by Olmsted and is listed
	1 Register, and southeast of the Zoo.
	FEATURES OF BUILDING AND SITE (including interior features if known): story brick and frame Dutch Colonial Revival style.
	side gambrel roof. Cornice end returns. Full-width
	osed porch. Rough cut, regular course stone base.
End bays have	paneled door flanked by 3/4 three-light sidelights. 12-light windows. Paneled apron. Doric pilaster
str	ips flank bays and entrance. Curved brackets over
19. DATE OF INITIA	CONSTRUCTION: c. 1910 pilasters support roof eave. Second floor has two
ARCHITECT: d	ouble hung 1/1 windows. Louvred window shutters.
В	and of trim below roof eave. Two pedimented gable
BUILDER:	ormers. Double-hung 1/1 windows in each dormer.
	DARCHITECTURAL IMPORTANCE: A fine example of vernacular
	Colonial Revival style residence with exaggerated mers. West Oakwood Place extends from Main Street
to Parkside Av	renue. At the northern border of the first section
	sion to be developed, the eastern portion of West eded to the city by Jacob Davis in 1887 and the
remainder by C	Caroline Jewett in 1888. West Oakwood closely
resembles a st	reet found in Olmsted's early 1870's maps of "The lile it does not connect with Jewett Avenue at the
park entrance	as Olmsted originally planned, it remains curvilinear
and as a cross and the park.	s street provides easy access to the main thoroughfares
21. SOURCES: Cit	ry Tax Assessor Field Sheets
	e Papers of Frederick Law Olmsted, Vol. III, by
	Charles E. Beveridge & David Schuyler, eds. (1983).
22. THEME:	

Dutch Colonial Revival