
BUILDING-STRUCTURE INVENTORY FORM	FOR OFFICE USE ONLY
DIVISION FOR HISTORIC PRESERVATION	UNIQUE SITE NO. <u>5413</u> DO
NEW YORK STATE PARKS AND RECREATION	QUAD
ALBANY, NEW YORK (518) 474-0479	SERIES
ALDANI, ALW TOKK (518) 4/4-04/9	NEG. NO
YOUR NAME: BUFFALO FRIENDS OF OLMSTED PAR	RKS DATE: July 16, 1984
P. O. BOX 590	DATE: <u>JULY 10, 1904</u>
YOUR ADDRESS:BUFFALO, NEW YORK 14205 - 0590	TELEBUONE.
YOUR ADDRESS:	TELEPHONE:
ORGANIZATION (if any):	
ORGANIZATION (if any):	
* * * * * * * * * * * * * * * * * * * *	
IDENTIFICATION	
1. BUILDING NAME(S): 2. COUNTY: Erie	Puffalo VILLACE
2. COUNTY: <u>ELLE</u> DWN/CITY.	VILLAGE:
3. STREET LOCATION:57 Oakwood € 4. OWNERSHIP: a. public □ b. private ☑	
5. PRESENT OWNER: Lois Riester	ADDRESS. 57 West Oakwood
6. USE: Original: <u>Residential</u>	Posidential
6. USE: Unginal: <u>Restdentiat</u>	Present: <u>Nesidencial</u>
7. ACCESSIBILITY TO PUBLIC: Exterior visible fro	om public road: Yes 🖾 No 🗆 e: Explain by permission
DESCRIPTION	e: Explain <u>21 Police 2000</u>
8. BUILDING a. clapboard \boxtimes b. stone \square	a brink a d board and botton
MATERIAL: e. cobblestone f. shingles	\mathbb{X} g. stucco \square other:
MATERIAL: e. coorestone i 1. siningies	
9. STRUCTURAL a. wood frame with interlocking	ioints 🗍
SYSTEM: b. wood frame with light mem	
(if known) c. masonry load bearing walls	
e other	
e. other	
e. other e. cother 10. CONDITION: a. excellent 🗆 b. good 🗵 c 11. INTEGRITY: a. original site 🗵 b. moved 🗆	fair d. deteriorated

12. РНОТО: 36-За





14.	THREATS TO BUILDING:	a. none known X b. zoning C c. roads C d. developers C e. deterioration C f. other: C C
15.	RELATED OUTBUILDING	S AND PROPERTY: a. barn b. carriage house c. garage d. privy e. shed f. greenhouse g. shop h. gardens
		i. landscape features: <u>tree and shrubs in front yard</u> j. other:
16.	SURROUNDINGS OF THE	BUILDING (check more than one if necessary): a. open land b. woodland c. scattered buildings d. d. densely built-up de. commercial f. industrial g. residential de f. industrial f. g. residential de f. commercial de f. commerc

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

(Indicate if building or structure is in an historic district)

Building is situated on a standard sized corner lot within Olmsted's Parkside subdivision. House is located three blocks from Delaware Park, which was designed by Olmsted and is listed on the National Register, and southeast of the Zoo.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known): Two and a half story Colonial Revival style. Front facing gable roof. Full-width flat-roof porch. Doric columns support entablature. Spindle balustrade. Glass paneled door flanked on one side by small double-hung leaded window. First floor double-hung 1/1 window. Second floor semi-hexagonal bay. Double-<u>SIGNIFICANCE</u> hung 1/1 windows. Glass paneled porch door. End 19. DATE OF INITIAL CONSTRUCTION: 1908 fluted Doric pilaster strips. Brackets under eave.

ARCHITECT: Pedimented gable, shingled, has three-part window. Double-hung 1/1 lights. Entablature window heads. BUILDER:

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: A gabled Colonial Revival style residence with Classical details applied. West Oakwood Place extends from Main Street to Parkside Avenue. At the northern border of the first section of the subdivision to be developed, the eastern portion of West Oakwood was deeded to the city by Jacob Davis in 1887 and the remainder by Caroline Jewett in 1888. West Oakwood closely resembles a street found in Olmsted's early 1870's maps of "The Parkside." While it does not connect with Jewett Avenue at the park entrance as Olmsted originally planned, it remains curvilinear and as a cross street provides easy access to the main thoroughfares and the park.

 SOURCES: City Building Permit Records City Tax Assessor Field Sheets Olmsted's Sketch Map of Buffalo, 1876 The Papers of Frederick Law Olmsted, Vol. III, by
THEME: Charles E. Beveridge & David Schuyler, eds. (1983).

Colonial Revival/ Classical Details