
BUILDING-STRUCTURE INVENTORY FORM	FOR OFFICE USE ONLY 029-40 D07		
	UNIQUE SITE NO. 5022 DOT		
DIVISION FOR HISTORIC PRESERVATION	QUAD		
NEW YORK STATE PARKS AND RECREATION	SERIES		
ALBANY, NEW YORK (518) 474-0479	NEG. NO		
YOUR NAME: Debra A. Mattice	DATE: <u>August 7, 1984</u>		
YOUR ADDRESS:37 Congress, Bflo, 1421	<u>3</u>		
ORGANIZATION (if any):City of Buffa	lo - Division of Planning		
* * * * * * * * * * * * * * * * * * *	* * * * * * * * * * * * * * * *		
1. BUILDING NAME (S):			
2. COUNTY: <u>Erie</u> TOWN/CITY: <u>B</u>	uffalo VILLACE:		
3. STREET LOCATION: 42 Tillin			
4. OWNERSHIP: a. public b. private 🖾			
5. PRESENT OWNER: Walter F. Alt	ADDRESS 42 Tillinghast Place Bfle		
6. USE: Original: <u>Residences</u>			
	rom public road: Yes 🕱 No 🗆		
	e: Explain <u>By Permission</u>		
DESCRIPTION			
8. BUILDING a. clapboard b. stone	c. brick d. board and batten		
MATERIAL: e. cobblestone 🗌 f. shingles	g. stucco 🖾 other:		
9. STRUCTURAL a. wood frame with interlocking			
SYSTEM: b. wood frame with light men			
(if known) c. masonry load bearing walls [			
d. metal (explain)	the second se		
e. other			
10. CONDITION: a. excellent D b. good 🗴	c. fair 🗌 d. deteriorated 🗌		
e. other 10. CONDITION: a. excellent $\Box$ b. good $\mathbf{x}$ 11. INTEGRITY: a. original site $\mathbf{x}$ b. moved $\Box$	c. fair d. deteriorated d		





14.	THREATS TO BUILDING:	a. none known 🖾 b. zoning 🗆 c. roads 🗔 d. developers 🗋 e. deterioration 🗔 f. other:
15.	RELATED OUTBUILDING	
		g. shop h. gardens h.
	SUBBOLIDING OF THE	j. other:
16.	SURROUNDINGS OF THE	BUILDING (check more than one if necessary): a. open land b. woodland c. scattered buildings d. d. densely built-up 🛛 e. commercial C
		f. industrial  g. residential  h. other:

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district) This building located at the eastern end of a long curvilinear east-west block is situated on a large building lot within Olmsted's Parkside subdivision. Single family residences, c. 1915, Craftsman, American Four Square, with moderate size lawns line this street. The grounds of the Buffalo Zoological Society are located

## 18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

One story Craftsman Bungalow. Front facing gable roof. Bargeboard with brackets under roof reak and eave ends. Partial width gabled porch. Rough cut regular coursed stone piers. Tapered square columns support roof. Stucco rail. Curved shape between porch supporch supports. Entrance flanked by sidelights. First floor windows, single light with transom. West side has Gabled oriel.

## SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1910

ARCHITECT:		 Levere .	and stranger to an	
BUILDER:				

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

4 4

Fine example of Craftsman Bungalow. The street takes its name from James Tillinghast owner of the property up until July 15, 1889 when it was conveyed to George L. Thorne and Byron Angell, to be subdivided for residential use. The subdivision named "Meadow View Park" carried restrictive covenants in its deeds of sale. The restrictions set forth minimum house costs and minimum measures for street frontage. The homes on Tillinghast were to be of "tasteful design" and the cost was not to be less than \$3,000. The street reflects Olmsted's philosophy regarding roadways located within a subdivision; Tillinghast is a broad, long roadway with no intersecting thoroughfares, running west to east "with no special directness toward the town."

21. SOURCES: Atlas of the City of Buffalo. 1894, 1915.

Deed - Liber 575, Page 143: Conveyance with restrictive covenants The Papers of Frederick Law Olmsted, Vol III, Pg 265.

22. THEME: Residential architecture associated with Parkside development Craftsman Bungalow