BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479


| FOR OFFICE USE ONLY | | |
|---------------------|------|------|
| UNIQUE SDENO40 | 5477 | D |
| SERIES | 10 | |
| NEG NO | | - 53 |

| ALDANY NEW YORK (\$10) 474 0470 | | |
|--|--|--|
| ALBANY, NEW YORK (518) 474-0479 NEG. NO | | |
| YOUR NAME: BUFFALO FRIENDS OF OLMSTED PARKS DATE: July 3, 1984 | | |
| YOUR NAME: DATE: July 3, 1984 P. O. BOX 590 | | |
| YOUR ADDRESS: BUFFALO, NEW YORK 14205 = 0590 TELEPHONE: | | |
| TOOK ADDRESSTELEFHONE | | |
| ORGANIZATION (if any): | | |
| 51.57 (ii alij). | | |
| * | | |
| IDENTIFICATION | | |
| 1. BUILDING NAME(S): | | |
| 2. COUNTY: Erie TOWN/CITY: Buffalo VILLAGE: | | |
| 3. STREET LOCATION: 60 Russell AVE | | |
| 4. OWNERSHIP: a. public 🗆 b. private 🔀 | | |
| 5. PRESENT OWNER: Rudolph Bova ADDRESS: 60 Russell | | |
| 6. USE: Original: Residential Present: Residential | | |
| 7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes 😾 No 🗆 | | |
| Interior accessible: Explain by permission | | |
| DESCRIPTION | | |
| 8. BUILDING a. clapboard \(\omega \) b. stone \(\omega \) c. brick \(\omega \) d. board and batten \(\omega \) | | |
| MATERIAL: e. cobblestone f. shingles g. stucco other: | | |
| 9. STRUCTURAL a. wood frame with interlocking joints | | |
| SYSTEM: b. wood frame with light members & | | |
| (if known) c. masonry load bearing walls | | |
| d. metal (explain) | | |
| e. other | | |
| 0. CONDITION: a. excellent b. good c. fair d. deteriorated | | |
| . CONDITION: a excellent \(\subseteq \) b. good \(\omega \) c. fair \(\subseteq \) d. deteriorated \(\subseteq \) . INTEGRITY: a original site \(\omega \) b. moved \(\supseteq \) if so,when? | | |
| c. list major alterations and dates (if known): | | |
| Porch supports and balustrade altered | | |

12. PHOTO: 39-6a



13. MAP:



| 14. | THREATS TO BUILDING: | a. none known 🕱 d. developers 🗆 f. other: | b. zoning □ c. roads □ e. deterioration □ |
|--|--|--|---|
| 15. | RELATED OUTBUILDINGS | S AND PROPERTY: a. barn b. car d. privy e. shee | riage house c. garage f. greenhouse dens tree and shrubs in front yard |
| 16. | SURROUNDINGS OF THE | BUILDING (check a. open land c. scattered buildings d. densely built-up f. industrial g. | e. commercial |
| Buil Park Dela | side subdivision | on a standar On a standar House is l was designed | district) rd sized lot within Olmsted's cocated two blocks from l by Olmsted and is listed on |
| Two Ful: ent: rect 1/1 | and a half story l-width flat roof rance has glass p tangular stained windows. Entabl | frame resided porch. Eave aneled door find glass window ature window second floor | AND SITE (including interior features if known): ence. Front facing gable roof. e overhang with dentils. Projecting flanked on one side by small . First floor paired double hung and door surround. Dentils under or semi-hexagonal bay with double- hung 1/1 windows. Glass and |
| | ARCHITECT: window gable BUILDER: 1/1 li | and door sur | wood paneled door. Plain rrounds. Band of trim below ented gable has pair double-hung Panel between windows. Entablature |
| resi exterin a Wash was this maps acce | HISTORICAL AND ARCHI idence found thro ends from Parksid a map of 1886, pa hington Russell, early 1889 befor s particular stre s of "The Parksid ess to major thor | rectural important aughout the But e Avenue to Caralleling the after whom the Russell Avenue tooes not a e," Olmsted froughfares and | ANCE: A typical frame gabled affalo area. Russell Avenue Greenfield Street. It was laid out a northern border of the lands of the street was named. However it enue was deeded to the city. While appear in Olmsted's early 1870's felt cross streets would allow easy it to the park, and he did include wett Avenue in his early plans. |
| 21. | Olmsted' | Assessor Fie s Sketch Map | |
| 22 | THEME: Charle | s E. Beverido | ge & David Schuyler, eds. (1983). |

Residence