BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479


FOR OFFICE USE ONLY 029-40 UNIQUE SITE NO.	5792	DC	7
QUAD			
SERIES			
NEG. NO.			-

ALBANY, NEW YORK (518) 474-0479 NEG. NO
YOUR NAME: BUFFALO FRIENDS OF OLMSTED PARKS DATE: JAN 1 0 1983
YOUR ADDRESS: BUFFALO, NEW YORK 14205 - 0590 TELEPHONE:
TOUR ADDRESS. SOUTHER TEAR 19203 - 0370 TELEFHONE.
ORGANIZATION (if any):
* * * * * * * * * * * * * * * * * * * *
IDENTIFICATION
1. BUILDING NAME(S):
2. COUNTY: Erie TOWN/CITY: Buffalo VILLAGE: 3. STREET LOCATION:145 Parkside Ave
3. STREET LOCATION: 145 Parkside Ave
4. OWNERSHIP: a. public □ b. private ☒
5. PRESENT OWNER: Charles S. Boone ADDRESS: 145 Parkside Avenue Residential Present: Residential
6. USE: Original: Residential Present: Residential
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes No Interior accessible: Explain by permission
DESCRIPTION DESCRIPTION
8. BUILDING a. clapboard 🛣 b. stone 🖾 c. brick 🗆 d. board and batten 🗆
MATERIAL: e. cobblestone f. shingles g. stucco other:
9. STRUCTURAL a. wood frame with interlocking joints
SYSTEM: b. wood frame with light members 🖫
(if known) c. masonry load bearing walls
d. metal (explain)
e. other
0. CONDITION: a. excellent b. good c. fair d. deteriorated
1. INTEGRITY: a. original site \(\overline{\text{D}} \) b. moved \(\overline{\text{D}} \) if so,when?
c. list major alterations and dates (if known):

12. PHOTO: 13 - 7



13. MAP:



14.	THREATS TO BUILDING: a. none known b. zoning c. roads e. deterioration e. deterioration
	Capi is 1 Mai f, other:
15.	RELATED OUTBUILDINGS AND PROPERTY: a. barn b. carriage house c. garage c. garage
	d. privy \(\subseteq \ e. \text{ shed } \(\subseteq \ f. \text{ greenhouse } \subseteq \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
	g. shop h. gardens trees & shrubs
	i. other:
16.	SURROUNDINGS OF THE BUILDING (check more than one if necessary): a. open land b. woodland
	c. scattered buildings
	d. densely built-up ☒ e. commercial ☐
	f. industrial g. residential A. h. other:
17.	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district) Building is situated on a
	standard sized city building lot within Olmsted's Parkside
	subdivision. House is directly opposite Delaware Park which
	was designed by Olmsted and is listed on the National Register.
18.	OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
10.	Two story American Four Square. Hip roof. Hipped dormers on
	south and west sides of house. Two bay windows on second floor
	of house front facade. Open porch with modillion-like brackets in the cornice and pre-cast fluted cement columns across front
	of house. Two mult-paned windows on the first floor front facade.
SIG	DATE OF INITIAL CONSTRUCTION: C. 1910
19.	DATE OF INITIAL CONSTRUCTION.
	ARCHITECT:
	BUILDER:
20.	HISTORICAL AND ARCHITECTURAL IMPORTANCE: Good example of the American
20.	Four Square style that was built in this neighborhood. This house
	is located on Parkside Avenue, a street conceived by FLO around 1873 as part of a residential "suburb" adjacent to Delaware Park.
	This suburb was called "The Parkside" by Olmsted and appears on an
	1876 map drawn by him as a proposed area of curved winding streets
	on the north and east sides of the park. Parkside Avenue was actually created by the City of Buffalo in 1888. The street very
	closely follows Olmsted's original plan maintaining the picturesque
	character that he envisioned for the streets surrounding the park.
	D. 55-1- Give 201 1004 1015
21.	SOURCES: Buffalo City Atlas 1894, 1915

22. THEME: American Four Square.

CHAUSC