
E	UILDING-STRUCTURE INVENTORY FORM	
	UILDING-STRUCTURE INVENTORY FORM	
	IVISION FOR HISTORIC PRESERVATION OUAD	
	Tew YORK STATE PARKS AND RECREATION SERIES	1
A	LBANY, NEW YORK (518) 474-0479 NEG. NO.	
		L
	YOUR NAME: BUFFALO FRIENDS OF OLMSTED PARKS DATE: July 3, 1984	
	P. O. BOX 590	
	YOUR ADDRESS: BUFFALO, NEW YORK 14205 = 0590 TELEPHONE:	
	ORGANIZATION (if any):	
*	* * * * * * * * * * * * * * * * * * * *	
	DENTIFICATION	
1	. BUILDING NAME (S):	
2	. COUNTY: Erie TOWN/CITY:Buffalo VILLAGE:	
3	STREET LOCATION: 74 Russell Ave	
	. OWNERSHIP: a. public 🗆 b. private 🖾	
	PRESENT OWNER: Michael Ernst ADDRESS: 74 Russell	
6	USE: Original: Residential Present: Residential	
7	ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes 🖾 No 🗆	
-	Interior accessible: Explain <u>by permission</u>	
	DESCRIPTION	
8	. BUILDING a. clapboard b. stone c. brick d. board and batten	
	MATERIAL: e. cobblestone 🗆 f. shingles 🗆 g. stucco 🗆 other: asbestos sidin	g
	2. STRUCTURAL a. wood frame with interlocking joints	
	SYSTEM: b. wood frame with light members 🖾	
	(if known) c. masonry load bearing walls	
	d. metal (explain)	
	e. other	
10	CONDITION: a. excellent \Box b. good \boxtimes c. fair \Box d. deteriorated \Box	
	. INTEGRITY: a. original site \boxtimes b. moved \square if so, when?	
1 25	c. list major alterations and dates (if known):	
	Porch remodeled	
	FOICH LEMODELED	

~

12. PHOTO: 39-1a

13. MAP:





14.	THREATS TO BUILDING:	a. none known b. zoning c. roads d. developers e. deterioration f. other:
15.	RELATED OUTBUILDING	S AND PROPERTY:
		a. barn D b. carriage house C c. garage 🖾
		d. privy 🗆 e. shed 🗆 f. greenhouse 🗆
		g. shop 🗋 h. gardens 🗌
		i. landscape features: small tree and hedge in front yard
		j. other:
16.	SURROUNDINGS OF THE	BUILDING (check more than one if necessary):
		a. open land 🗆 b. woodland 🗆
		c. scattered buildings
		d. densely built-up 🖾 e. commercial 🗆
		f. industrial 🔲 g. residential 🙀
		h. other:

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

(Indicate if building or structure is in an historic district) Building is situated on a standard sized lot within Olmsted's Parkside subdivision. House is located two blocks from Delaware Park, which was designed by Olmsted and is listed on the National Register, and east of the Zoo.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known): Two and a half story Princess Anne residence. Side gable roof with cornice end returns. Full-width flat roof porch with eave overhang. Square pier supports at porch corners. Boxed left bay first floor has paired single hung windows with diamond shaped tracery in top light. Light recessed bay has glass and wood paneled door. Second floor has 1-1/2 story gabled boxed bay. Cornice end <u>SIGNIFICANCE</u> 19. DATE OF INITIAL CONSTRUCTION: 1903 returns. Paired single hung,

single light windows on ARCHITECT: second floor and gable. Right bay second floor has three-light wood door flanked on one side by single BUILDER: light sidelight. Shed roof hood. Hip roof dormer has single-hung window, diamond tracery in top light.

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: Pilaster strips flank window. Princess Anne residence embodies asymmetrical shape and relatively simple, unornamented surfaces. Russell Avenue extends from Parkside Avenue to Greenfield Street. It was laid out in a map of 1886, paralleling the northern border of the lands of Washington Russell, after whom the street was named. However it was early 1889 before Russell Avenue was deeded to the city. While this particular street does not appear in Olmsted's early 1870's maps of "The Parkside," Olmsted felt cross streets would allow easy access to major thoroughfares and to the park, and he did include similar cross streets such as Jewett Avenue in his early plans.

21.	SOURCES:	City Building Permit Records
		Buffalo Address Book, 1904
		Olmsted's Sketch Map of Buffalo, 1876
		The Papers of Frederick Law Olmsted, Vol. III, by
22.	THEME:	Charles E. Beveridge & David Schuyler, eds. (1983).

Princess Anne