## BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479


FOR OFFICE USE ONLY O29-40 UNIQUE SITE NO.	4840	D07
QUAD		
SERIES		
NEG. NO.		

NEG. NO.
YOUR NAME: BUFFALO FRIENDS OF OLMSTED PARKS DATE: February 3, 198
YOUR ADDRESS: BUFFALO, NEW YORK 14205 = 0590 TELEPHONE:
ORGANIZATION (if any):
* * * * * * * * * * * * * * * * * * * *
IDENTIFICATION
1. BUILDING NAME(S):
1. BUILDING NAME(S): 2. COUNTY:ErieTOWN/CITY:BuffaloVILLAGE:
3. STREET LOCATION: 76 Clescent Ave
4. OWNERSHIP: a. public □ b. private ☒
5. PRESENT OWNER: Gopinath Kartha ADDRESS: 76 Crescent
6. USE: Original: Residential Present: Residential
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes 🗵 No 🗆
Interior accessible: Explain by permission
DESCRIPTION
8. BUILDING a. clapboard \( \subseteq \) b. stone \( \subseteq \) c. brick \( \subseteq \) d. board and batten \( \subseteq \)
MATERIAL: e. cobblestone ☐ f. shingles ☒ g. stucco ☐ other:
9. STRUCTURAL a. wood frame with interlocking joints
SYSTEM: b. wood frame with light members 🗵
(if known) c. masonry load bearing walls
d. metal (explain)
e. other
0. CONDITION: a. excellent □ b. good ☒ c. fair □ d. deteriorated □
1. INTEGRITY: a. original site \( \overline{\mathbb{Z}} \) b. moved \( \overline{\mathbb{D}} \) if so, when?
c. list major alterations and dates (if known):
Capitals of porch columns replaced with wood
blocks

12. PHOTO: 9-17a



13. MAP:



14.	THREATS TO BUILDING: a. none known  b. zoning  c. roads  c. roads
	RELATED OUTBUILDINGS AND PROPERTY:  a. barn  b. carriage house  c. garage  d. privy  e. shed  f. greenhouse  g. shop  h. gardens  i. landscape features: shrubs in front yard; hedge i. other:
16.	SURROUNDINGS OF THE BUILDING (check more than one if necessary):  a. open land  b. woodland  c. scattered buildings  d. densely built-up  e. commercial  f. industrial  g. residential  h. other:
17.	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
Pa: De:	(Indicate if building or structure is in an historic district)  ilding is situated on a standard sized lot within Olmsted's rkside subdivision. House is located two blocks from laware Park, which was designed by Olmsted and is listed on a National Register, and southeast of the Zoo.
Cla pi sh	OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known): assical Revival with hip roof and hip roof dormers. Fluted laster corner boards. Dormers have fish-scale patterned wood ingles. Classical doorway has leaded glass sidelights. tensive leaded glass in second story.
	NIFICANCE  DATE OF INITIAL CONSTRUCTION: 1907
	ARCHITECT:
	BUILDER:
lor fro Oli pl cu fir 18 Av	HISTORICAL AND ARCHITECTURAL IMPORTANCE: Crescent Avenue is the ngest curvilinear street in the Parkside subdivision, stretching om Humboldt Avenue to Colvin Street. This street appears on msted's early 1870's maps of "The Parkside." By the 1880's ans for Crescent Avenue had been modified by Olmsted to its rrent form. Portions of the street were deeded to the city by we different owners over a span of five years, beginning in 87 near Humboldt and ending in 1892 near Colvin. Crescent enue begins and ends within the Parkside subdivision, following msted's rule that a suburban neighborhood street "not lead with ecial directness toward the town."
21.	SOURCES: City Tax Assessor Field Sheets Olmsted's Sketch Map of Buffalo, 1876 The Papers of Frederick Law Olmsted, Vol. III, by Charle E. Beveridge & David Schuyler, eds. (1983).

22. THEME: Classical Revival