BUILDING-STRUCTURE INVENTORY FORM


DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479

| FOR OFFICE USE ONLY O29-40 UNIQUE SITE NO. OUAD | 5610 | DO7 |
|---|------|-----|
| SERIESNEG. NO | | |

| ALBANY, NEW YORK (518) 474-0479 | NEG. NO. |
|--|--|
| YOUR NAME: BUFFALO FRIENDS OF OLMSTED PARPLE P. O. BOX 590 | DATE: July 3, 1984 |
| YOUR ADDRESS: BUFFALO, NEW YORK 14205 = 0590 | TELEPHONE: |
| ORGANIZATION (if any): | |
| * * * * * * * * * * * * * * * * * * * | * * * * * * * * * * * * * * |
| IDENTIFICATION | |
| 1. BUILDING NAME(S): | |
| 2. COUNTY: Erie TOWN/CITY: 3. STREET LOCATION: 95 Russell AV | Buffalo VILLAGE: |
| 3. STREET LOCATION: 95 Russell AV | e |
| 4. OWNERSHIP: a. public □ b. private ☒ | |
| 5. PRESENT OWNER: Raul Nunez | ADDRESS: 95 Russell |
| 6. USE: Original: Residential | Present: Residential |
| 7. ACCESSIBILITY TO PUBLIC: Exterior visible | from public road: Yes 😾 No 🗆 |
| Interior accessib | ole: Explain by permission |
| DESCRIPTION | |
| 8. BUILDING a. clapboard □ b. stone □ | ☐ c. brick ☐ d. board and batten ☐ |
| MATERIAL: e. cobblestone f. shingles | s 🗆 g. stucco 🗆 other: asbestos siding |
| 9. STRUCTURAL a. wood frame with interlocking SYSTEM: b. wood frame with light mer | ng joints 🗆 |
| SYSTEM: b. wood frame with light mer | mbers 🗵 |
| (if known) c. masonry load bearing walls | |
| | |
| e. other | |
| 0. CONDITION: a. excellent □ b. good ☒ | |
| 1. INTEGRITY: a. original site ☒ b. moved ☐ | if so,when? |
| c. list major alterations and dates (i | if known): |

12. PHOTO: 38-10a





| 14. THREATS TO BUILDIN | G: a. none known b. zoning c. roads d. developers e. deterioration f. other: |
|--|--|
| 15. RELATED OUTBUILDIN | |
| 16. SURROUNDINGS OF T | HE BUILDING (check more than one if necessary): a. open land b. woodland c. scattered buildings d. densely built-up e. commercial f. industrial g. residential h. other: |
| (Indicate if building or si Building is situa Olmsted's Parksid from Delaware Par | OF BUILDING AND SURROUNDINGS: tructure is in an historic district) ted on a standard sized corner lot within e subdivision. House is located three blocks k, which was designed by Olmsted and is listed egister, and east of the Zoo. |
| Two and a half st width shed roof p balustrade. 12-1 window. Right ba | TURES OF BUILDING AND SITE (including interior features if known): ory frame with front facing gable roof. Full- orch. Doric column supports and spindle ight wood door flanked on one side by 1/1 y has double-hung 1/1 window. Plain window floor has two double-hung 6/1 windows. Plain surround. Pedimented gable with triangular astruction. c. 1903 knee brackets at ends of |
| ARCHITECT: | projection. Bargeboard. Double hung 6/1 window. |
| | |
| BUILDER: | |
| 20. HISTORICAL AND ARC residence. Russe Greenfield Street the northern bord whom the street was Russell Avenue was street does not a Parkside," Olmste to major thorough | |

Residence