BUILDING-STRUCTURE INVENTORY FORM


DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY UNIQUE SITE NO.	5511	007
QUAD		
SERIES		
NEG. NO.		-

NEG. NO.
YOUR NAME: BUFFALO FRIENDS OF OLMSTED PARKS DATE: July 3, 1984
YOUR ADDRESS: BUFFALO, NEW YORK 14205 = 0590 TELEPHONE:
ORGANIZATION (if any):
* * * * * * * * * * * * * * * * * * * *
IDENTIFICATION
1. BUILDING NAME(S): 2. COUNTY: Erie TOWN/CITY:Buffalo VILLAGE:
2. COUNTY:
3. STREET LOCATION: 99 Russell AVE
4. OWNERSHIP: a. public □ b. private ☒
5. PRESENT OWNER: Stella Sawyer ADDRESS: 99 Russell
6. USE: Original: Residential Present: Residential
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes 🛣 No 🗆
Interior accessible: Explain by permission
DESCRIPTION
8. BUILDING a. clapboard \(\bar{k} \) b. stone \(\) c. brick \(\) d. board and batten \(\)
MATERIAL: e. cobblestone f. shingles g. stucco other:
MATERIAL. C. COORDICTION II II. SHINGLO LEE G. STUCCO LE CHIEF.
9. STRUCTURAL a. wood frame with interlocking joints
(if known) c. masonry load bearing walls
d. metal (explain)
e. other
0. CONDITION: a. excellent b. good c. fair d. deteriorated
1. INTEGRITY: a. original site 🖾 b. moved 🗌 if so,when?
c list major alterations and dates (if known):

12. РНОТО: 38-11а





14. THREATS TO BUILDING: a. none known 🖾 b. zoning 🗆 c. roads 🗆	7.		
d. developers e. deterioration f. other:			
15. RELATED OUTBUILDINGS AND PROPERTY:			
a. barn □ b. carriage house □ c. garage □			
d. privy □ e. shed □ f. greenhouse □			
g. shop h. gardens			
i. landscape features: <u>tree</u> and shrubs in front yard j. other:			
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):			
a. open land □ b. woodland □			
c. scattered buildings			
d. densely built-up 💂 e. commercial 🗌			
f. industrial g. residential \(\omega \)			
n. outer.			
17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:			
(Indicate if building or structure is in an historic district)			
Building is situated on a standard sized corner lot within			
Olmsted's Parkside subdivision. House is located three blocks			
from Delaware Park, which was designed by Olmsted and is listed on the National Register, and east of the Zoo.			
18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known): Two and a half story frame with front facing gable roof. Full			
width gabled porch. Rough cut, regular course stone base. Squa	are		
Doric end supports. Stick balustrade. Gable, shingled, with			
stick styling. Bargeboard with flared ends. Three-light wood			
paneled door in left bay first floor. Three-part window, center	r		
SIGNIFICANCE 12/1 light with 9/1 sides. Entablature window and			
19. DATE OF INITIAL CONSTRUCTION: c. 1910 door surround. Second floor	OOL		
left and right bay has ARCHITECT: paired double hung 9/1 windows. Entablature window			
surrounds. Pediment shaped panel spans second floor	or.		
BUILDER: Doric end pilaster strips. Gable with cornice end			
returns. Bargeboard. Stick styling. Three-part			
20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: window; center 1/1 with			
A gabled frame residence with 9/1 sides.			
Craftsman and Colonial Revival style detailing. Russell Avenue extends from Parkside Avenue to Greenfield Street. It was laid			
out in a map of 1886, paralleling the northern border of the			
lands of Washington Russell, after whom the street was named.			
However it was early 1889 before Russell Avenue was deeded to			
the city. While this particular street does not appear in			
Olmsted's early 1870's maps of "The Parkside," Olmsted felt cross streets would allow easy access to major thoroughfares			
and to the park, and he did include similar cross streets such			
as Jewett Avenue in his early plans.			
21. SOURCES: Buffalo Address Book, 1915			
Olmsted's Sketch Map of Buffalo, 1876			
The Papers of Frederick Law Olmsted, Vol. III, by			
Charles E. Beveridge & David Schuyler, eds. (1983)	•		

Residence