## **BUILDING-STRUCTURE INVENTORY FORM**


DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY		DO
UNIQUE SITE NO.	5487	
QUAD		
SERIES		
NEG. NO.		

ALBANY, NEW YORK (518) 474-0479 NEG. NO
YOUR NAME: BUFFALO FRIENDS OF OLMSTED PARKS P. O. BOX 590  DATE: July 3, 1984
YOUR ADDRESS: BUFFALO, NEW YORK 14205 = 0590 TELEPHONE:
ORGANIZATION (if any):
* * * * * * * * * * * * * * * * * * * *
IDENTIFICATION
1. BUILDING NAME(S): 2. COUNTY: Erie TOWN/CITY: Buffalo VILLAGE:
3. STREET LOCATION: 102 Russell AVE
4. OWNERSHIP: a. public □ b. private ⊠
5. PRESENT OWNER: Jolles Barnes Jr. ADDRESS: 102 Russell
6. USE: Original: Residential Present: Residential
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes 🗵 No 🗆
Interior accessible: Explain by permission
DESCRIPTION
8. BUILDING a. clapboard  b. stone  c. brick d. board and batten
MATERIAL: e. cobblestone  f. shingles g. stucco other:
9. STRUCTURAL a. wood frame with interlocking joints
SYSTEM: b. wood frame with light members \( \bar{\mathbb{L}} \)
(if known) c. masonry load bearing walls
d. metal (explain)
e. other
0. CONDITION: a. excellent □ b. good ☒ c. fair □ d. deteriorated □
1. INTEGRITY: a. original site ☒ b. moved ☐ if so, when?
c list major alterations and dates (if known):

12. PHOTO: 38-34a





14. THREATS TO BUILDING: a. none known  b. zoning  c. roads  c. deterioration  c. roads  c. roads  c. roads  c. deterioration  c. roads  c. roads  c. deterioration  c. roads  c	
15. RELATED OUTBUILDINGS AND PROPERTY:  a. barn □ b. carriage house □ c. garage ☑  d. privy □ e. shed □ f. greenhouse □	
g. shop  h. gardens  i. landscape features: tree and shrubs in front yard j. other:	
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):  a. open land □ b. woodland □  c. scattered buildings □	
d. densely built-up ⊠ e. commercial □  f. industrial □ g. residential ☑  h. other:	
17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district)	
Building is situated on a standard sized lot within Olmsted's Parkside subdivision. House is located three blocks from Delaware Park, which was designed by Olmsted and is listed on the National Register, and east of the Zoo.	
18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known): Two and a half story frame with Colonial Revival styling. Front facing gable roof with cornice end returns. Full-width flat roof porch. Rough cut, regular course stone base. Square Doric supports. Paneled rail. Entablature with cornice overhang. Dentils Boxed projecting entrance bay. Glass and wood paneled door. Entrance SIGNIFICANCE flanked by double hung 1/1 windows. First floor left bay	26
19. DATE OF INITIAL CONSTRUCTION: 1901 has three part window. Center single hung window with leaded ARCHITECT: top light. Double hung 1/1 sides. Entablature window surrounds. Second floor has two semi-hexagonal bays.	Ĺ
BUILDER: Double hung 1/1 windows. Plain window surrounds. Band of trim below gable. Modillion style brackets under	1
A frame, with Palladian window. Pedimented gable dormer with cornice end returns	5.
Russell Avenue extends from Parkside Avenue to Greenfield Street. It was laid out in a map of 1886, paralleling the northern border of the lands of Washington Russell, after whom the street was named. However it was early 1889 before Russell Avenue was deeded to the city. While this particular street does not appear in Olmsted's early 1870's maps of "The Parkside," Olmsted felt cross streets would allow easy access to major thoroughfares and to the park, and he did include similar cross streets such as Jewett Avenue in his early plans.	
21. SOURCES: City Building Permit Records Buffalo Address Book, 1901 Olmsted's Sketch Map of Buffalo, 1876 The Papers of Frederick Law Olmsted, Vol. III, by  22. THEME: Charles E. Beveridge & David Schuyler, eds. (1983).	

Colonial Revival Styling