BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479


FOR OFFICE USE ONLY	DO	1
UNIQUE SITE NO. 56303		
QUAD SERIES	_	
NEG. NO.		

YOUR NAME: BUFFALO FRIENDS OF OLMSTED PARKS DATE: JAN 1 0 1983
P. O. BOX 590
YOUR ADDRESS: BUFFALO, NEW YORK 14205 - 0590 TELEPHONE:
ORGANIZATION (if any):
* * * * * * * * * * * * * * * * * * * *
IDENTIFICATION (C)
1. BUILDING NAME(S): 2. COUNTY: Erie TOWN/CITY: Buffalo VILLAGE:
3. STREET LOCATION: 191 Parkside Ave
4. OWNERSHIP: a. public b. private \(\overline{\mathbb{X}}\)
5. PRESENT OWNERSalvatore Mattina ADDRESS: 191 Parkside Avenue
6. USE: Original: Residential Present: Residential
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes No
Interior accessible: Explain by permission
DESCRIPTION
8. BUILDING a. clapboard b. stone c. brick d. board and batten
8. BUILDING a. clapboard b. stone c. brick d. board and batten a. cobblestone f. shingles g. stucco other:
9. STRUCTURAL a. wood frame with interlocking joints
SYSTEM: b. wood frame with light members 🔯
(if known) c. masonry load bearing walls
d. metal (explain)
e. other
10. CONDITION: a. excellent \(\subseteq \) b. good \(\subseteq \) c. fair \(\subseteq \) d. deteriorated \(\subseteq \)
11. INTEGRITY: a. original site \(\overline{\
c. list major alterations and dates (if known): windows filled in w.

12. РНОТО: 13-19

13. MAP:





14.	THREATS TO BUILDING: a, none known \(\bar{\sqrt{L}} \) d. developers \(\bar{\sqrt{L}} \) e. deterioration \(\bar{\sqrt{L}} \)
	d. developers : c. deterioration :
15.	RELATED OUTBUILDINGS AND PROPERTY:
	a. barn b. carriage house c. garage d. privy e. shed f. greenhouse
	g shop h gardens
	i. landscape features:
	j. other:
16.	a. open land b. woodland
	c. scattered buildings
	d. densely built-up 🗵 e. commercial 🗆
	f. industrial g. residential h. other:
	n. oulet .
17.	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
	(Indicate if building or structure is in an historic district)
	lding is situated on a standard sized city building lot within sted's Parkside subdivision. House is directly opposite Delaware
	k which was designed by Olmsted and is listed on the National Register.
18.	OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Two	story brick house. Hip roof with a hipped dormer on front facade.
	mer has three six light over single pane windows. First and second or windows are six light over single pane windows. Porte cochere
	south side of house. Recessed entranceway under porter cochere
	a multi-paned door. House is brick veneer.
SIG	NIFICANCE TO THE PROPERTY OF T
19.	DATE OF INITIAL CONSTRUCTION: C. 1915
	ARCHITECT:
	BUILDER:
	HISTORICAL AND ARCHITECTURAL IMPORTANCE:
20th	ical example of a brick house built in this neighborhood in the early century. This house is located on Parkside Avenue, a street con-
cei	wed by FLO around 1873 as part of a residential "suburb" adjacent to

Typical example of a brick house built in this neighborhood in the early 20th century. This house is located on Parkside Avenue, a street conceived by FLO around 1873 as part of a residential "suburb" adjacent to Delaware Park. This suburb was called "The Parkside" by Olmsted and appears on an 1876 map drawn by him as a proposed area of curved winding streets on the north and east sides of the park. Parkside Avenue was actually created by the City of Buffalo in 1888. The street very closely follows Olmsted's original plan maintaining the picturesque character that he envisioned for the streets surrounding the park.

- 21. SOURCES: Buffalo City Atlas 1915
 Sanborn Map 1916
 Buffalo Index to Streets c. 1896
- 22. THEME: Brick house.