BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479


FOR OFFICE USE ONLY	
UNIQUE SITE NO. 578	<u>D</u> 07
SERIESNEG. NO	

	YOUR NAME: BUFFALO FRIENDS OF OLMSTED PARKS DATE: March 30, 1984
	P. O. BOX 590
	YOUR ADDRESS: BUFFALO, NEW YORK 14205 = 0590 TELEPHONE:
	100K 1100K 100K 14203 - U3YU
	ORGANIZATION (if any):
	ORGANIZATION (II ally).
*	
ID	DENTIFICATION
_	BUILDING NAME (S):
1.	COUNTY: Erie TOWN/CITY: Buffalo VILLAGE:
2.	COUNTY: BITE TOWN/CITY: BULLAGE:
3.	STREET LOCATION: 143 Woodward Ave
4.	OWNERSHIP: a. public b. private 3
5.	PRESENT OWNER: Lewis Lipka ADDRESS: 143 Woodward
6.	USE: Original: Residential Present: Residential
7.	ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes 🖾 No 🗆
	Interior accessible: Explain by permission
_	ESCRIPTION
8.	BUILDING a. clapboard \(\omega \) b. stone \(\omega \) c. brick \(\omega \) d. board and batten \(\omega \)
	MATERIAL: e. cobblestone ☐ f. shingles ☑ g. stucco ☐ other:
9	STRUCTURAL a. wood frame with interlocking joints
	SYSTEM: b. wood frame with light members 🗵
	(if known) c. masonry load bearing walls
	d. metal (explain)
	e. other
0.	CONDITION: a. excellent b. good c. fair d. deteriorated
1.	INTEGRITY: a. original site \(\omega \) b. moved \(\omega \) if so, when?
	c. list major alterations and dates (if known):

12. PHOTO: 23-31a



13. MAP:



14.	THREATS TO BUILDING: a. none known ☑ b. zoning □ c. roads □ e. deterioration □
	f. other:
15	RELATED OUTBUILDINGS AND PROPERTY:
15.	a. barn □ b. carriage house □ c. garage ☒
	d. privy e. shed f. greenhouse
	g. shop h. gardens
	i. landscape features: small tree in front yard
	j. other:
16.	SURROUNDINGS OF THE BUILDING (check more than one if necessary):
	a. open land \square b. woodland \square
	c. scattered buildings
	d. densely built-up e. commercial
	f. industrial g. residential A. h. other:
	n. other.
17	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
17.	(Indicate if building or structure is in an historic district)
B11	ilding is situated on a standard sized lot within Olmsted's
Pai	ckside subdivision. House is located one block from
	laware Park, which was designed by Olmsted and is listed on the
	cional Register, and southeast of the Zoo.
18	OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Тълс	and a half story American Four Square. Hip roof with rafter
ta	ils under eave. Full-width gable roof porch. Square Doric
sur	oports with column elaboration. Stick balustrade. Projecting
ent	crance has glass and wood paneled door flanked by small
red	ctangular leaded window. Boxed bay on first floor has single
OR CI	light with leaded transom window. Second floor has
19	DATE OF INITIAL CONSTRUCTION: 1912 prism-shaped tracery in top light. Entablature window
• • •	light. Entablature window
	ARCHITECT: surround. Horizontal band course at second floor.
	Hip roof dormer, exposed rafter tails. Three
	BUILDER: windows with prism-shaped tracery in top light.
20	HISTORICAL AND ARCHITECTURAL IMPORTANCE: Typical American Four
20.	uare. Woodward Avenue runs parallel to Parkside Avenue and
54	tends from Humboldt Avenue to the northwest portion of Crescent
Av	enue. This street appears on Olmsted's early 1870's maps of
"m"	he Parkside," although it is less curvilinear than originally
pla	anned. Portions of Woodward Avenue (originally called Davis
Av	enue) were deeded to the city by five different owners between
18	87 and 1892; except for the section north of Amherst, this was
do	ne when comparable sections of Crescent Avenue were deeded.
Fo	llowing Olmsted's rule for a suburban street, Woodward Avenue
do	es "not lead with special directness toward town."

City Building Permit Records 21. SOURCES: City Tax Assessor Field Sheets Olmsted's Sketch Map of Buffalo, 1876 The Papers of Frederick Law Olmsted, Vol. III, by 22. THEME:

Charles E. Beveridge & David Schuyler, eds. (1983).