## **BUILDING-STRUCTURE INVENTORY FORM**


DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY 029-40 UNIQUE SITE NO	5560	D07
SERIESNEG. NO		1 "

YOUR NAME: BUFFALO FRIENDS OF OLMSTED PARKS P.O. BOX 590 YOUR ADDRESS: BUFFALO, NEW YORK 14205 - 0590 TELEPHONE:  ORGANIZATION (if any):  ** * * * * * * * * * * * * * * * * *	ALBANY, NEW YORK (518) 474-0479	NEG. NO.	
ORGANIZATION (if any):  * * * * * * * * * * * * * * * * * * *	YOUR NAME: BUFFALO FRIENDS OF OLMSTED PARKS P. O. BOX 590	DATE: <u>April 23, 1984</u>	
Note	YOUR ADDRESS: BUFFALO, NEW YORK 14205 - 0590	TELEPHONE:	
Note   Description   Description	ODCANIZATION (S		
BUILDING NAME (S):	ORGANIZATION (II any):		
1. BUILDING NAME (S):	* * * * * * * * * * * * * * * * * * * *	* * * * * * * * * * * * * *	
2. COUNTY:	IDENTIFICATION		
3. STREET LOCATION: 269 Summit AVE 4. OWNERSHIP: a. public  b. private  5. PRESENT OWNER: James McGoldrick ADDRESS: 269 Summit 6. USE: Original: Residential Present: Residential 7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes  No Interior accessible: Explain by permission  DESCRIPTION 8. BUILDING  a. clapboard  b. stone  c. brick  d. board and batten  material  e. cobblestone  f. shingles  g. stucco  other:  9. STRUCTURAL  a. wood frame with interlocking joints  system:  b. wood frame with light members  c. masonry load bearing walls  d. metal (explain)  e. other  0. CONDITION: a. excellent  b. good  c. fair  d. deteriorated  1. INTEGRITY: a. original site  b. moved  if so, when?	1. BUILDING NAME(S):		
4. OWNERSHIP: a. public  b. private  5. PRESENT OWNER:  James McGoldrick  ADDRESS:  269 Summit  6. USE: Original:  Residential  Present:  Residential  7. ACCESSIBILITY TO PUBLIC:  Exterior visible from public road: Yes  No  Interior accessible:  Explain  by permission  DESCRIPTION  8. BUILDING  a. clapboard  b. stone  c. brick  d. board and batten  MATERIAL:  e. cobblestone  f. shingles  g. stucco  other:  9. STRUCTURAL  a. wood frame with interlocking joints  system:  b. wood frame with light members  System:  b. wood frame with light members  c. masonry load bearing walls  d. metal (explain)  e. other  souther:  1. INTEGRITY:  a. original site  b. moved  if so,when?	2. COUNTY: Erie TOWN/CITY: B	uffalo_VILLAGE:	
5. PRESENT OWNER: James McGoldrick ADDRESS: 269 Summit 6. USE: Original: Residential Present: Residential 7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes No Interior accessible: Explain by permission  DESCRIPTION 8. BUILDING a. clapboard b. stone c. brick d. board and batten a. cobblestone f. shingles g. stucco other:  9. STRUCTURAL a. wood frame with interlocking joints system: b. wood frame with light members d. c. masonry load bearing walls d. metal (explain) e. other  0. CONDITION: a. excellent b. good c. fair d. d. deteriorated 1. INTEGRITY: a. original site b. moved if so, when?			
6. USE: Original: Residential Present: Residential 7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes No Interior accessible: Explain by permission  DESCRIPTION 8. BUILDING a. clapboard b. stone c. brick d. board and batten matter and batten systems.  9. STRUCTURAL a. wood frame with interlocking joints systems: b. wood frame with light members systems: b. wood frame with light members systems: c. masonry load bearing walls d. metal (explain) e. other  0. CONDITION: a. excellent b. good c. fair d. d. deteriorated 1. INTEGRITY: a. original site b. moved 1. if so, when?			
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes No Interior accessible: Explain by permission  DESCRIPTION  8. BUILDING			
DESCRIPTION   S. BUILDING   a. clapboard   b. stone   c. brick   d. board and batten   matter   system:   b. wood frame with interlocking joints   system:   b. wood frame with light members   system:   c. masonry load bearing walls   d. metal (explain)   e. other   c. fair   d. deteriorated   so, when?   so, when?	6. USE: Original: Residential Pre	sent: Residential	
BUILDING MATERIAL:  a. clapboard ☑ b. stone □ c. brick □ d. board and batten □ e. cobblestone □ f. shingles □ g. stucco □ other:  9. STRUCTURAL SYSTEM: (if known)  c. masonry load bearing walls □ d. metal (explain) e. other  e. other  1. INTEGRITY: a. original site ☑ b. moved □ if so,when?	7. ACCESSIBILITY TO PUBLIC: Exterior visible from	public road: Yes X No L	
8. BUILDING MATERIAL:  a. clapboard \( \) b. stone \( \) c. brick \( \) d. board and batten \( \)  9. STRUCTURAL SYSTEM: (if known)  c. masonry load bearing walls \( \) d. metal (explain) e. other  0. CONDITION: a. excellent \( \) b. good \( \) c. fair \( \) d. deteriorated \( \) 1. INTEGRITY: a. original site \( \) b. moved \( \) if so,when?		Explain by permission	
MATERIAL:  e. cobblestone  f. shingles g. stucco other:  9. STRUCTURAL SYSTEM: b. wood frame with interlocking joints c. masonry load bearing walls d. metal (explain) e. other  0. CONDITION: a. excellent b. good c. fair d. d. deteriorated .  1. INTEGRITY: a. original site b. moved if so,when?			
9. STRUCTURAL SYSTEM: b. wood frame with light members  c. masonry load bearing walls  d. metal (explain) e. other  0. CONDITION: a. excellent  b. good  c. fair  d. deteriorated  1. INTEGRITY: a. original site  b. moved  if so,when?	8. BUILDING a. clapboard 🗷 b. stone 🗆	c. brick \( \square \) d. board and batten \( \square \)	
SYSTEM:  (if known)  c. masonry load bearing walls   d. metal (explain)  e. other  0. CONDITION:  a. excellent   b. good   c. fair   d. deteriorated   1. INTEGRITY:  a. original site   b. moved   if so,when?	MATERIAL: e. cobblestone ☐ f. shingles ☐	g. stucco U other:	
SYSTEM:  (if known)  c. masonry load bearing walls   d. metal (explain)  e. other  0. CONDITION:  a. excellent   b. good   c. fair   d. deteriorated   1. INTEGRITY:  a. original site   b. moved   if so,when?	() CERLICIURAL a wood from with interleaking in	:t. □	
c. masonry load bearing walls  d. metal (explain)  e. other  0. CONDITION: a. excellent  b. good  c. fair  d. deteriorated  1. INTEGRITY: a. original site  b. moved  if so,when?			
d. metal (explain)		3 🗀	
e. other			
0. CONDITION: a. excellent □ b. good ☒ c. fair □ d. deteriorated □ 1. INTEGRITY: a. original site ☒ b. moved □ if so, when?			
1. INTEGRITY: a. original site ☒ b. moved ☐ if so,when?	O CONDITION: a. excellent D b. good \( \) c. f.	air \( \square \) d. deteriorated \( \square \)	
c. list major alterations and dates (if known):	I INTEGRITY: a. original site 🗵 b. moved	if so, when?	
	c. list major alterations and dates (if kn	nown):	

12. РНОТО: 26-27а





14.	THREATS TO	D BUILDING: a. none known ☑ b. zoning ☐ c. roads ☐
		d. developers  e. deterioration  f. other:
15	RELATED OF	UTBUILDINGS AND PROPERTY:
1	KEEMTED	a. barn b. carriage house c. garage 🗵
		d. privy □ e. shed □ f. greenhouse □
		g. shop  h. gardens
		i. landscape features: <u>tree</u> and shrubs in front yard
17	CHIDDOLINIO	j. other:
16.	SURROUNDI	a. open land \( \sigma \) b. woodland \( \sigma \)
		c. scattered buildings
		d. densely built-up 🗵 e. commercial 🗆
		f. industrial 🗆 g. residential 🖾
		h. other:
	n menner i	TIONISHIP OF BUILDING AND CURROUNDINGS.
1/.		TIONSHIP OF BUILDING AND SURROUNDINGS: uilding or structure is in an historic district)
Rini		situated on a standard sized lot within Olmsted's
		bdivision. House is located two blocks from
		rk, which was designed by Olmsted and is listed on
the	e Nationa	1 Register, and northeast of the Zoo.
18.	OTHER NOT	ABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Two	and a h	alf story American Four Square form with Colonial
Rev	vival sty	ling. Hip roof. Symmetrical facade. Flat-roof
ent	rance po	rch has fluted Doric columns supporting entablature.
Sty	rlized na	turalistic forms decorate frieze. Dentils under
		tick balustrade. Glass and wood paneled door with
SIGN	NIFICANCE	single light sidelights. First and second floor
19.	DATE OF IN	ITIAL CONSTRUCTION: c. 1894 8/8 light windows.  Center second floor 1/1
	ARCHITECT	window. Hip roof dormer
	ARCHITECT	with pair of double hung
	BUILDER:_	windows, 6/6 light and 1/1 light.
		AND ARCHITECTURAL IMPORTANCE: A typical American Four
		dence with Colonial Revival styling applied to facade. ue is a truncated north-south street, located between
		d Crescent Avenues and extending from West Oakwood
		e northern section of Crescent Avenue. A similar
		ing south of Jewett Avenue, appears in Olmsted's
ear	ly 1870's	s maps of "The Parkside." Summit Avenue was deeded
to	the city	in 1889, except for the small section between
		Crescent which was deeded in 1892. This street
	ard the	sted's rule that it "not lead with special directness
LOW	ard the	LOWII.
21.	SOURCES:	Buffalo City Atlas, 1894
		City Tax Assessor Field Sheets
		Olmsted's Sketch Map of Buffalo, 1876
		The Papers of Frederick Law Olmsted, Vol. III, by
22.	THEME:	Charles E. Beveridge & David Schuyler, eds. (1983).
		American Four Square/ Colonial Revival Styling