BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479


FOR OFFICE USE ONLY UNIQUE SITE NO. 4991	D07
QUADSERIES	
NEG. NO.	

L BUILDING NAME (S):
YOUR ADDRESS: BUFFALO, NEW YORK 14205 = 0590 TELEPHONE: ORGANIZATION (if any):
ORGANIZATION (if any):
* * * * * * * * * * * * * * * * * * *
* * * * * * * * * * * * * * * * * * *
IDENTIFICATION 1. RUIL DING NAME (S):
IDENTIFICATION 1. RUIL DING NAME (S):
L BUILDING NAME (S):
1. BUILDING NAME(S): 2. COUNTY: Erie TOWN/CITY: Buffalo VILLAGE:
2. COUNTY: Erie TOWN/CITY: Buffalo VILLAGE:
4. OWNERSHIP: a. public □ b. private ☑
5. PRESENT OWNER: Alan Ryer ADDRESS: 223 Crescent
6. USE: Original: Residential Present: Residential
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes 🗵 No 🗆
Interior accessible: Explain by permission
DESCRIPTION
8. BUILDING a. clapboard b. stone c. brick d. board and batten
MATERIAL: e. cobblestone f. shingles g. stucco other: asbestos
O CERTICEURAL a word from with interded him in int.
9. STRUCTURAL a. wood frame with interlocking joints SYSTEM. b. wood frame with light mambars STRUCTURAL
SYSTEM: b. wood frame with light members (if known) c. masonry load bearing walls
(if known) c. masonry load bearing walls d. metal (explain)
e. other
0. CONDITION: a. excellent \(\Boxed{D} \) b. good \(\Boxed{Z} \) c. fair \(\Doxed{D} \) d. deteriorated \(\Doxed{D} \)
1. INTEGRITY: a. original site 🖾 b. moved 🗀 if so,when?

12. PHOTO: 10-6a



13. MAP:



14.		d. developers e. deterioration f. other:
15. 1	RELATED OUTBUILDINGS	S AND PROPERTY:
		a. barn □ b. carriage house □ c. garage ☒ d. privy □ e. shed □ f. greenhouse □
		g. shop h. gardens h. greenhouse
		i. landscape features: shrubs in front yard
17 (CUBBOUNDINGS OF THE	j. other:BUILDING (check more than one if necessary):
16.	SURROUNDINGS OF THE	a. open land \(\sigma \) b. woodland \(\sigma \)
		c. scattered buildings
		d. densely built-up 😾 e. commercial 🗆 f. industrial 🗆 g. residential 🔯
		h. other:
	WEEDER ATTOMOUNT OF	NULL DING AND SUBBOUNDINGS.
		BUILDING AND SURROUNDINGS: ture is in an historic district)
Buil	ding is situated	on a standard sized lot within Olmsted's
Park	side subidivision	n. House is located three blocks from was designed by Olmsted and is listed on
the	National Register	r, and southeast of the Zoo.
		RES OF BUILDING AND SITE (including interior features if known):
Two	and a half story	residence with front facing gable roof.
Full	-width porch, hip	p roof. A pair of double glass doors. gle light center with 1/1 sidelights.
Seco	and floor boxed ba	ay with tri-part window imitating first
f100	r Pedimented a	able has tri-part window. 30/1 center and
SIGNI	IFICANCE 25/1 sides	s. Cornice window head. Terra-cotta RUCTION: c. 1905 chimney pots.
19.	DATE OF INITIAL CONSTR	RUCTION: <u>C. 1905</u>
-	ARCHITECT:	
	BUILDER:	
		TECTURAL IMPORTANCE: Plain residence with Anne style. Crescent Avenue is the longest
curv	vilinear street in	n the Parkside subdivision, stretching from
		olvin Street. This street appears on 's maps of "The Parkside." By the 1880's
plan	ns for Crescent A	venue had been modified by Olmsted to its
curr	cent form. Portion	ons of the street were deeded to the city by
five	near Humboldt a	s over a span of five years, beginning in and ending in 1892 near Colvin. Crescent
Aver	nue begins and en	ds within the Parkside subdivision, following
Olms	sted's rule that	a suburban neighborhood street "not lead

22. THEME:

Residence/ Queen Anne Influence

Olmsted's Sketch Map of Buffalo, 1876

The Papers of Frederick Law Olmsted, Vol. III, by

Charles E. Beveridge & David Schuyler, eds. (1983).

21. SOURCES: County Census Records, 1905