## **BUILDING-STRUCTURE INVENTORY FORM**


DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY  020-40  UNIQUE SITE NO.	55V8	D	07
QUAD		_	
SERIES	-	_	
NEG. NO.		_	

ALBANY, NEW YORK (518) 474-0479 NEG. NO
YOUR NAME: BUFFALO FRIENDS OF OLMSTED PARKS DATE: April 23, 1984
.P. O. BOX 590
YOUR ADDRESS: BUFFALO, NEW YORK 14205 - 0590 TELEPHONE:
ORGANIZATION (if any):
* * * * * * * * * * * * * * * * * * * *
DENTIFICATION
I. BUILDING NAME(S):
1. BUILDING NAME(S):
3. STREET LOCATION: 299 Summit Ave 4. OWNERSHIP: a. public \( \square\) b. private \( \sqrare\)
4. OWNERSHIP: a. public  b. private
5. PRESENT OWNER: Henry Kabel ADDRESS: 299 Summit 6. USE: Original: Residential Present: Residential
5. USE: Original: Residential Present: Residential
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes 😾 No 🗌
Interior accessible: Explain by permission
DESCRIPTION
8. BUILDING a. clapboard \( \bar{\bar{\bar{\bar{\bar{\bar{\bar{
MATERIAL: e. cobblestone □ f. shingles □ g. stucco □ other:
9. STRUCTURAL a. wood frame with interlocking joints
SYSTEM: b. wood frame with light members 🖾
(if known) c. masonry load bearing walls
d. metal (explain)
e. other
0. CONDITION: a. excellent  b. good  c. fair d. deteriorated
1. INTEGRITY: a. original site ☑ b. moved ☐ if so, when?
c. list major alterations and dates (if known):
Porch has been enclosed

12. PHOTO: 26-35a





14.	THREATS TO BUILDING: a. none known  b. zoning  c. roads  c. roads  e. deterioration  f. other:
15.	RELATED OUTBUILDINGS AND PROPERTY:  a. barn  b. carriage house  c. garage  d. privy  e. shed  f. greenhouse    g. shop  h. gardens  i. landscape features: small tree and shrubs in front yarding other:
16.	SURROUNDINGS OF THE BUILDING (check more than one if necessary):  a. open land  b. woodland  c. scattered buildings  d. densely built-up  e. commercial  f. industrial  g. residential  h. other:
Bui	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:  (Indicate if building or structure is in an historic district)  Ilding is situated on a standard sized corner lot within  insted's Parkside subdivision. House is located two blocks  om Delaware Park, which was designed by Olmsted and is listed  the National Register, and northeast of the Zoo.
roc st: sq: Sei	OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known): o and a half story frame residence with front facing gable of. Full-width flat roof porch, partially enclosed. Pilaster rips flank 4 single light windows. Recessed entrance with ware doric corner support. Two glass and wood paneled doors. mi-hexagonal bay on second floor, 1/1 windows. Glass and wood paneled porch door. Stick balustrade. Pedimented DATE OF INITIAL CONSTRUCTION:
	ARCHITECT:
	BUILDER:
Bu st ex Cre Ave Sur sm. 18	HISTORICAL AND ARCHITECTURAL IMPORTANCE: A typical gabled frame ffalo residence. Summit Avenue is a truncated north-south reet, located between Woodward and Crescent Avenues and tending from West Oakwood Place to the northern section of escent Avenue. A similar street, ending south of Jewett enue, appears in Olmsted's early 1870's maps of "The Parkside." mmit Avenue was deeded to the city in 1889, except for the all section between Amherst and Crescent which was deeded in 92. This street follows Olmsted's rule that it "not lead th special directness toward the town."
21.	SOURCES: City Building Permit Records Olmsted's Sketch Map of Buffalo, 1876 The Papers of Frederick Law Olmsted, Vol. III, by Charles E. Beveridge & David Schuyler, eds. (1983).

22. THEME:

Residence