
DUIL DING STRUCTURE INVENTORY FORM	FOR OFFICE USE ONLY
BUILDING-STRUCTURE INVENTORY FORM	029-40 5810 D07
DIVISION FOR HISTORIC PRESERVATION	UNIQUE SITE NO 5810 LOT
NEW YORK STATE PARKS AND RECREATION	QUAD
ALBANY, NEW YORK (518) 474-0479	SERIES
ALBANT, NEW TORK (518) 474-0479	NEG. NO
YOUR NAME: BUFFALO FRIENDS OF OLMSTED PAR	PKS DATE March 30, 1984
P. O. BOX 590	DATE
YOUR ADDRESS: BUFFALO, NEW YORK 14205 - 0590	TELEPHONE:
ORGANIZATION (if any):	
* * * * * * * * * * * * * * * * * * * *	* * * * * * * * * * * * * * *
IDENTIFICATION	
1. BUILDING NAME (S):	
2. COUNTY: <u>Erie</u> TOWN/CITY 3. STREET LOCATION: <u>291 Woodward</u>	BuffaloVILLAGE:
3. STREET LOCATION:291 Woodward	e
4. OWNERSHIP: a. public 🗆 b. private 🖾	
5. PRESENT OWNER: Aloizs Pusmucans	ADDRESS: 1063 Amherst, Buffalo, N
6. USE: Original: Residential	Present: <u>Residential</u> 1421
7. ACCESSIBILITY TO PUBLIC: Exterior visible fr	rom public road : Yes 🖾 No 🗀
Interior accessibl	le: Explain by permission
DESCRIPTION	
8. BUILDING a. clapboard b. stone	
MATERIAL: e. cobblestone \Box f. shingles	g. stucco other: vinyl siding
9. STRUCTURAL a. wood frame with interlockin	a joints
SYSTEM: b. wood frame with light mem	
(if known) c. masonry load bearing walls	
e. other	
10. CONDITION: a. excellent \Box b. good \mathbf{x}	c. fair 🗌 d. deteriorated 🗔
	if so,when?
	ii ao, wiich:
c. list major alterations and dates (if	f known).

12. PHOTO: 24-19a





14.	THREATS TO BUILDING:	a. none known 🖄 b. zoning 🗆 c. roads 🗆 d. developers 🔲 e. deterioration 🗔 f. other:
15.	RELATED OUTBUILDING	a. barn b. carriage house c. garage d. privy e. shed f. greenhouse c
		g. shop h. gardens i. landscape features: <u>tree and shrubs in front yard</u> j. other:
16.	(that more than one if pacesant):	

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district)

Building is situated on a standard sized corner lot within Olmsted's Parkside subdivision. House is located one block from Delaware Park, which was designed by Olmsted and is listed on the National Register, and east of the Zoo.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known): Two and a half story with details relating to Colonial Revival style. Steep-pitch front-facing gable roof. Full-width enclosed porch. Flat roof. Horizontal band of 4/1 light windows. Vertical clapboard in apron. Glass and wood paneled door. Second floor has semi-hexagonal bay window. Square-headed 1/1 windows. Plain window surround. Pedimented gable has brackets under SIGNIFICANCE projection. Tri-part window, 19. DATE OF INITIAL CONSTRUCTION: 1904 1/1 lights. Entablature window head with projecting ARCHITECT: cornice. South side has pedimented gable bay. BUILDER:

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: Woodward Avenue runs parallel to Parkside Avenue and extends from Humboldt Avenue to the northwest portion of Crescent Avenue. This street appears on Olmsted's early 1870's maps of "The Parkside," although it is less curvilinear than originally planned. Portions of Woodward Avenue (originally called Davis Avenue) were deeded to the city by five different owners between 1887 and 1892; except for the section north of Amherst, this was done when comparable sections of Crescent Avenue were deeded. Following Olmsted's rule for a suburban street, Woodward Avenue does "not lead with special directness toward town."

21. SOURCES: City Building Permit Records City Tax Assessor Field Sheets Olmsted's Sketch Map of Buffalo, 1876 The Papers of Frederick Law Olmsted, Vol. III, by Charles E. Beveridge & David Schuyler, eds. (1983). 22. THEME:

Colonial Revival Details