
	A COLORED AND A COLOR
DUIL DINC STRUCTURE INVENTORY FORM	FOR OFFICE USE ONLY
BUILDING-STRUCTURE INVENTORY FORM	020 10 00
DIVISION FOR HISTORIC PRESERVATION	UNIQUE SITE NO. 9-40 5716
NEW YORK STATE PARKS AND RECREATION	QUAD
ALBANY, NEW YORK (518) 474-0479	SERIES
ALDAN 1, NEW TORK (518) 4/4-04/9	NEG. NO
YOUR NAME: BUFFALO FRIENDS OF OLMSTED PARE	<b>(S)</b> DATE: March 30, 1984
P. O. BOX 590	DITL.
YOUR ADDRESS: BUFFALO, NEW YORK 14205 - 0590	TELEPHONE:
ORGANIZATION (if any):	
* * * * * * * * * * * * * * * * * * * *	* * * * * * * * * * * * * * * *
IDENTIFICATION	
I. BUILDING NAME (S):	
2. COUNTY: Erie TOWN/CITY: H	SUITALOVILLAGE:
3. STREET LOCATION: <u>304 Woodward A</u>	VO
4. OWNERSHIP: a. public b. private	
5. PRESENT OWNER: John Simon	ADDRESS: <u>304 Woodward</u>
6. USE: Original: <u>Residential</u>	Present: <u>Residential</u>
7. ACCESSIBILITY TO PUBLIC: Exterior visible fr	om public road: Yes 🖾 No 🗆
DESCRIPTION Interior accessible	e: Explain <u>by permission</u>
8. BUILDING a. clapboard 🖾 b. stone 🗆	c. brick $\Box$ d. board and batten $\Box$
MATERIAL: e. cobblestone i f. shingles	g. stucco 🗌 other:
9. STRUCTURAL a. wood frame with interlocking	ģioints 🗆
SYSTEM: b. wood frame with light mem	
(if known) c. masonry load bearing walls	
e. other	
0. CONDITION: a. excellent 🗌 b. good 🗵 c	. fair 🗌 d. deteriorated 🗌
	if so, when?
c. list major alterations and dates (if	known):
Porch removed	

13. MAP:

12. PHOTO: 21-33a





17

n217

1

1'P

T D

T

299

	2	
14.	THREATS TO BUILDING:	a. none known 🖾 b. zoning 🗆 c. roads 🗆
		d. developers 🗆 e. deterioration 🗆
		f. other:
15.	RELATED OUTBUILDING	a. barn □ b. carriage house □ c. garage k
		d. privy 🗌 e. shed 🗍 f. greenhouse 🗌
		g. shop $\Box$ h. gardens $\Box$
		i. landscape features: tree and shrubs in front yard
		j. other:
16.	SURROUNDINGS OF THE	BUILDING (check more than one if necessary):
		a. open land 🗌 b. woodland 🗌
		c. scattered buildings
		d. densely built-up 🖾 e. commercial 🗌
		f. industrial 🗆 g. residential 🖾
		h. other:

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

(Indicate if building or structure is in an historic district)

Building is situated on a standard sized lot within Olmsted's Parkside subdivision. House is located one block from Delaware Park, which was designed by Olmsted and is listed on the National Register, and east of the Zoo.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known): Two and a half story later, simplified form of the Queen Anne style. Hip roof. Steep-pitched gabled wing has brackets under eave. Wood paneled door with entablature door surround. Dentils under cornice. Leaded window to right of entrance. First and second floor 1/1 light windows. Gable has false pediment with dentils. Tri-part window with decorative diamondshaped tracery. Threestory semi-hexagonal bay

ARCHITECT:	with polygonal tent roof
	on south side.

BUILDER: \_\_\_\_\_\_\_\_ 20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: A typical, simple version of Queen Anne style. Woodward Avenue runs parallel to Parkside Avenue and extends from Humboldt Avenue to the northwest portion of Crescent Avenue. This street appears on Olmsted's early 1870's maps of "The Parkside," although it is less curvilinear than originally planned. Portions of Woodward Avenue (originally called Davis Avenue) were deeded to the city by five different owners between 1887 and 1892; except for the section north of Amherst, this was done when comparable sections of Crescent Avenue were deeded. Following Olmsted's rule for a suburban street, Woodward Avenue does "not lead with special directness

 21. SOURCES: City Tax Assessor Field Sheets County Census Records, 1905 Olmsted's Sketch Map of Buffalo, 1876 The Papers of Frederick Law Olmsted, Vol. III, by
22. THEME: Charles E. Beveridge & David Schuyler, eds. (1983).

Queen Anne

toward town."