BUILDING-STRUCTURE INVENTORY FORM


FOR OFFICE USE ONLY		
UNIQUE SITE NOO	5727	-007
SERIESNEG. NO		-

DIVISION FOR HISTORIC PRESERVATION	QUAD	
NEW YORK STATE PARKS AND RECREATION	SERIES	
ALBANY, NEW YORK (518) 474-0479	NEG. NO.	
BUFFALO FRIENDS OF OLMSTED PAR		
YOUR NAME: P. O. BOX 590	DATE: March 30, 1984	
YOUR ADDRESS: BUFFALO, NEW YORK 14205 = 0590	TELEPHONE:	
ORGANIZATION (if any):		
* * * * * * * * * * * * * * * * * * * *	* * * * * * * * * * * * * * * *	
IDENTIFICATION (C)		
1. BUILDING NAME(S):	Duffala Invitor	
2. COUNTY: Erie TOWN/CITY:	BUITATO VILLAGE:	
3. STREET LOCATION: 356 Woodward 4. OWNERSHIP: a. public □ b. private ☑	ve	
4. OWNERSHIP: a. public ☐ b. private ☑		
5. PRESENT OWNER: Andrew Mahoney		
6. USE: Original: Residential		
7. ACCESSIBILITY TO PUBLIC: Exterior visible fr	rom public road: Yes 🛭 No 🗆	
Interior accessible	e: Explain <u>by permission</u>	
DESCRIPTION		
8. BUILDING a. clapboard b. stone	c. brick d. board and batten	
MATERIAL: e. cobblestone f. shingles	☐ g. stucco 🔀 other:	
	_	
9. STRUCTURAL a. wood frame with interlocking		
SYSTEM: b. wood frame with light mem		
(if known) c. masonry load bearing walls		
d. metal (explain)		
e. other		
0. CONDITION: a. excellent b. good b. good	c. fair \(\square \) d. deteriorated \(\square \)	
1. INTEGRITY: a. original site ☒ b. moved ☐	if so, when?	
c. list major alterations and dates (if	known):	
Upper porch balustra	de altered	
d. metal (explain) e. other 0. CONDITION: a. excellent b. good 1. INTEGRITY: a. original site b. moved c. list major alterations and dates (if	c. fair d. deteriorated fiso,when?	

12. PHOTO: 22-7a



13. MAP:



14.	THREATS TO BUILDING:	a. none known \(\omega \) b. zoning \(\omega \) c. roads \(\omega \) d. developers \(\omega \) e. deterioration \(\omega \) f. other: \(\omega \)
	RELATED OUTBUILDING	S AND PROPERTY: a. barn b. carriage house c. garage d. privy e. shed f. greenhouse g. shop h. gardens i. landscape features: trees and shrubs in front yard
16.	SURROUNDINGS OF THE	BUILDING (check more than one if necessary): a. open land b. woodland c. scattered buildings d. densely built-up e. commercial f. industrial g. residential h. other:
20,2	(Indicate if building or stru	BUILDING AND SURROUNDINGS: cture is in an historic district)
Oli	msted's Parkside om Delaware Park,	d on a standard sized corner lot within subdivision. House is located one block which was designed by Olmsted and is listed ister, and east of the Zoo.
Tw galwi ba li	o and a half storble roof with module the return. Partilustrade. Pedime ght door. Small First a DATE OF INITIAL CONST	RES OF BUILDING AND SITE (including interior features if known): y plain residential structure. Front facing illion blocks under raking cornice. Cornice al width porch has square end piers, stick inted entrance. Cornice end returns. Multi- rectangular 6 light window on second floor. and second floor has multi-light porch door with flanking multi-light windows. Tri-part 6 light
	ARCHITECT:	windows.
	BUILDER:	
th ru to on is Wo th fo se ru sp	at makes use of Cons parallel to Pathe northwest pool of Constead's early less curvilinear odward Avenue (or e city by five directions of Crescer le for a suburbance of Constead directness SOURCES: City But Olmstead The Page	Colonial Revival details. Woodward Avenue crkside Avenue and extends from Humboldt Avenue artion of Crescent Avenue. This street appears 1870's maps of "The Parkside," although it than originally planned. Portions of riginally called Davis Avenue) were deeded to ferent owners between 1887 and 1892; except th of Amherst, this was done when comparable to Avenue were deeded. Following Olmsted's street, Woodward Avenue does "not lead with toward town." Wilding Permit Records I's Sketch Map of Buffalo, 1876 Deers of Frederick Law Olmsted, Vol. III, by the E. Beveridge & David Schuyler, eds. (1983).
	Plain F	Residential Structure