## BUILDING-STRUCTURE INVENTORY FORM.

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479


FOR OFFICE USE ONLY		
UNIQUE SITE NO40	5751	-DOT
SERIES		
NEG. NO.		_

NEG. NO		
YOUR NAME: BUFFALO FRIENDS OF OLMSTED PARKS DATE: March 30, 1984 P. O. BOX 590		
YOUR ADDRESS: BUFFALO, NEW YORK 14205 - 0590 TELEPHONE:		
ORGANIZATION (if any):		
* * * * * * * * * * * * * * * * * * * *		
IDENTIFICATION		
1. BUILDING NAME(S):  2. COUNTY: TOWN/CITY: Buffalo VILLAGE:		
2. COUNTY: TOWN/CITY: Buffalo VILLAGE:		
3. STREET LOCATION: 466 Woodward 4. OWNERSHIP: a. public  b. private  ve		
4. OWNERSHIP: a. public \( \subseteq \) b. private \( \times \)		
5. PRESENT OWNER: Robert Hopkins ADDRESS: 466 Woodward		
6. USE: Original: Residential Present: Residential		
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes No		
DESCRIPTION Interior accessible: Explain by permission		
8. BUILDING - a. clapboard \( \bar{\bar{\bar{\bar{\bar{\bar{\bar{		
MATERIAL: e. cobblestone  f. shingles g. stucco other:		
MATERIAL. C. COUDICATORIC II 1. SIMILET B. STUCCO II OTHER.		
9. STRUCTURAL a. wood frame with interlocking joints		
SYSTEM: b. wood frame with light members 🖾		
(if known) c. masonry load bearing walls		
d. metal (explain)		
e. other		
10. CONDITION: a. excellent □ b. good ☒ c. fair □ d. deteriorated □		
11. INTEGRITY: a. original site \( \Big \) b. moved \( \Big \) if so, when?		
c. list major alterations and dates (if known):		

12. PHOTO: 22-31a



13. MAP:



14. THREATS TO BUILDING: a. none known ☑ b. zoning □ c. roads □ d. developers □ e. deterioration □ f. other:
15. RELATED OUTBUILDINGS AND PROPERTY:  a. barn  b. carriage house  c. garage  d. privy  e. shed  f. greenhouse    g. shop  h. gardens  i. landscape features: large trees and shrubs in front yar
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):  a. open land □ b. woodland □  c. scattered buildings □  d. densely built-up ☑ e. commercial □  f. industrial □ g. residential ☑  h. other: □
17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:  (Indicate if building or structure is in an historic district)
Building is situated on a standard sized lot within Olmsted's Parkside subdivision. House is located one block from Delaware Park, which was designed by Olmsted and is listed on the National Register, and northeast of the Zoo.
18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):  Two and a half story American Four Square. Hip roof. Full-width porch has square supports, panel rails, entablature. Upper porch has stick-styled balustrade. Glass paneled door flanked by elliptical leaded window. First and second floor has paired square-headed 1/1 windows. Glass paneled porch door. Hip roof  SIGNIFICANCE dormer has a pair of windows with prism-shaped tracery in top light.
ARCHITECT:
BUILDER:
20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: Typical American Four Square with Colonial Revival style details applied. Woodward Avenue runs parallel to Parkside Avenue and extends from Humboldt Avenue to the northwest portion of Crescent Avenue. This street appears on Olmsted's early 1870's maps of "The Parkside," although it is less curvilinear than originally planned. Portions of Woodward Avenue (originally called Davis Avenue) were deeded to the city by five different owners between 1887 and 1892; except for the section north of Amherst, this was done when comparable sections of Crescent Avenue were deeded. Following Olmsted's rule for a suburban street, Woodward Avenue does "not lead with special directness toward town."
21. SOURCES: City Building Permit Records City Tax Assessor Field Sheets Olmsted's Sketch Map of Buffalo, 1876 The Papers of Frederick Law Olmsted, Vol. III, by Charles E. Beveridge & David Schuyler, eds. (1983).

American Four Square/Colonial Revival Details