
BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479


FOR OFFICE USE ONI UNIQUE SITE NO.	LY 5080	DO
QUAD		
SERIES NEG. NO		

NEG. NO	_
YOUR NAME: BUFFALO FRIENDS OF OLMSTED PARKS DATE: February 3, 1	984
YOUR ADDRESS: BUFFALO, NEW YORK 14205 = 0590 TELEPHONE:	
ORGANIZATION (if any):	
* * * * * * * * * * * * * * * * * * * *	*
IDENTIFICATION	
1. BUILDING NAME (S):	
1. BUILDING NAME(S):	
3. STREET LOCATION: 667 Crescent Ave	
4. OWNERSHIP: a. public □ b. private ☒	
5. PRESENT OWNER: Mary Guerra ADDRESS: 667 Crescent	
6. USE: Original: Residential Present: Residential	
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes No Interior accessible: Explain by permission	
DESCRIPTION DESCRIPTION	
8. BUILDING a. clapboard \(\omega \) b. stone \(\square \) c. brick \(\square \) d. board and batten	П
MATERIAL: e. cobblestone ☐ f. shingles ☒ g. stucco ☐ other:	_
9. STRUCTURAL a. wood frame with interlocking joints	
SYSTEM: b. wood frame with light members \(\omega \)	
(if known) c. masonry load bearing walls	
d. metal (explain)	
e. other	
0. CONDITION: a. excellent □ b. good ☒ c. fair □ d. deteriorated □	
1. INTEGRITY: a. original site 🗵 b. moved 🗆 if so, when?	
c. list major alterations and dates (if known):	

12. РНОТО: 7-6а



13. MAP:



14. THREATS TO BUILDING: a. none known ⊠ b. zoning □ c. roads □ d. developers □ e. deterioration □ f. other:
15. RELATED OUTBUILDINGS AND PROPERTY: a. barn □ b. carriage house □ c. garage ☒ d. privy □ e. shed □ f. greenhouse □ g. shop □ h. gardens □ i. landscape features: small tree and shrubs in front yard i. other:
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary): a. open land b. woodland c. scattered buildings d. densely built-up e. commercial f. industrial g. residential h. other:
17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district)
Building is situated on a standard sized lot within Olmsted's Parkside subdivision. House is located two blocks from Delaware Park, which was designed by Olmsted and is listed on the National Register, and north of the Zoo.
18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known): Two story Dutch Colonial Revival style. Side gambrel roof with flared ends and projecting eaves. Shed roof dormer, over-scale, has exposed rafter tails under eave. Exterior brick chimney interrupts dormer. 6/6 square-headed windows with surrounds. First floor 6/6 windows. Partial-width trellised porch has SIGNIFICANCE slender, square doric supports with ornamental trellis
19. DATE OF INITIAL CONSTRUCTION: 1922 work. 12-light double sash door. Trellised entrance
ARCHITECT: hood on east side supported by brackets.
BUILDER:
20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: Typical vernacular adaptation of Dutch Colonial Revival style. Similar to 711 Crescent in building design. Crescent Avenue is the longest curvilinear street in the Parkside subdivision, stretching from Humboldt Avenue to Colvin Street. This street appears on Olmsted's early 1870's maps of "The Parkside." By the 1880's plans for Crescent Avenue had been modified by Olmsted to its current form. Portions of the street were deeded to the city by five different owners over a span of five years, beginning in 1887 near Humboldt and ending in 1892 near Colvin. Crescent Avenue begins and ends within the Parkside subdivision, following Olmsted's rule that a suburban neighborhood street "not lead"
21. SOURCES: with special directness toward the town." City Building Permit Records City Tax Assessor Field Sheets Olmsted's Sketch Map of Buffalo, 1876
21. SOURCES: with special directness toward the town." City Building Permit Records City Tax Assessor Field Sheets

Dutch Colonial Revival