## **BUILDING-STRUCTURE INVENTORY FORM**

DIVISION FOR HISTORIC PRESERVATION NEW YORK STATE PARKS AND RECREATION ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY 029-40 UNIQUE SITE NO.	5087	DO	7
SERIES NEG. NO	t-		

NEG. NO.
YOUR NAME: BUFFALO FRIENDS OF OLMSTED PARKS DATE: February 3, 198
P. O. BOX 590
YOUR ADDRESS: BUFFALO, NEW YORK 14205 - 0590 TELEPHONE:
ORGANIZATION (if any):
* * * * * * * * * * * * * * * * * * * *
IDENTIFICATION
1. BUILDING NAME(S):
1. BUILDING NAME(S):  2. COUNTY: Erie TOWN/CITY: Buffalo VILLAGE:  3. STREET LOCATION: 695 Crescent AVE
3. STREET LOCATION: 695 Crescent Ave
4. OWNERSHIP: a. public □ b. private ☒
5. PRESENT OWNER: Paul Hausle ADDRESS: 695 Crescent
6. USE: Original: Residential Present: Residential
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes No Interior accessible: Explain by permission
DESCRIPTION
8. BUILDING a. clapboard \( \bar{\subset} \) b. stone \( \bar{\subset} \) c. brick \( \bar{\subset} \) d. board and batten \( \bar{\subset} \)  MATERIAL: e. cobblestone \( \bar{\subset} \) f. shingles \( \bar{\subset} \) g. stucco \( \bar{\subset} \) other:
9. STRUCTURAL a. wood frame with interlocking joints
SYSTEM: b. wood frame with light members 🖾
(if known) c. masonry load bearing walls  d. metal (explain)
e. other
10. CONDITION: a. excellent □ b. good ☒ c. fair □ d. deteriorated □
11. INTEGRITY: a. original site 🗵 b. moved 🗌 if so,when?
c. list major alterations and dates (if known):


13. MAP:

## 12. РНОТО: 7-13а



HP-1

## CRESCENT AV.



14.	THREATS TO BUILDING: a. none known  b. zoning  c. roads  c. roads  e. deterioration  f. other:		
	RELATED OUTBUILDINGS AND PROPERTY:  a. barn  b. carriage house c. garage d. d. privy e. shed f. greenhouse g. shop h. gardens i. landscape features: shrubs in front yard i. other:		
16.	SURROUNDINGS OF THE BUILDING (check more than one if necessary):  a. open land  b. woodland  c. scattered buildings  d. densely built-up  d. e. commercial  f. industrial  g. residential  h. other:		
17.	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district)		
Building is situated on a standard sized lot within Olmsted's Parkside subdivision. House is located two blocks from Delaware Park, which was designed by Olmsted and is listed on the National Register, and north of the Zoo.			
Two Par car mul 9	OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known): of and a half story residential structure. Side gable roof. ortial width porch has square supports, entablature with oping cornice. Multi-light double sash door flanked by a light sidelights. Porch cornice extends to end entrance. Light wood paneled door. Tri-part first floor window, 6/1 lights. Shingled second floor. Square-headed 6/1 DATE OF INITIAL CONSTRUCTION: 1923 light windows. Shutters.		
	ARCHITECT: Gabled dormer with triangular cornice ends. 1/1 light		
	BUILDER: Clyde Lanctot		
strin to 18° Ave Por own and with a string to 18° and t	HISTORICAL AND ARCHITECTURAL IMPORTANCE: A plain frame residential ructure. Crescent Avenue is the longest curvilinear street the Parkside subdivision, stretching from Humboldt Avenue Colvin Street. This street appears on Olmsted's early 70's maps of "The Parkside." By the 1880's plans for Crescent enue had been modified by Olmsted to its current form. In the street were deeded to the city by five different mers over a span of five years, beginning in 1887 near Humboldt dending in 1892 near Colvin. Crescent Avenue begins and ends with the Parkside subdivision, following Olmsted's rule that suburban neighborhood street "not lead with special directness ward the town."		
	SOURCES: City Building Permit Records City Tax Assessor Field Sheets Olmsted's Sketch Map of Buffalo, 1876 The Papers of Frederick Law Olmsted, Vol. III, by THEME: Charles E. Beveridge & David Schuyler, eds. (1983).		

Residence