

	BUILDING-STRUCTURE INVENTORY FORM	FOR OFFICE USE ONLY DO7		
	DIVISION FOR HISTORIC PRESERVATION	UNIQUE SITE NO. 5095		
	NEW YORK STATE PARKS AND RECREATION	QUAD		
	ALBANY, NEW YORK (518) 474-0479	SERIES		
	(100 mm, 100 FORK (310) 4/404/)	NEG. NO		
	YOUR NAME: BUFFALO FRIENDS OF OLMSTED PAR	C DATE February 3 1984		
	P. O. BOX 590	BATE. TEDILALY 5, 1904		
	YOUR ADDRESS: BUFFALO, NEW YORK 14205 - 0590	TELEPHONE		
	100K ADDRESS 10KK 14203 - 0390			
*	ORGANIZATION (if any):			
	· · · · · · · · · · · · · · · · · · ·			
	* * * * * * * * * * * * * * * * * * * *	* * * * * * * * * * * * * * /		
	IDENTIFICATION			
	1. BUILDING NAME (S):			
	2. COUNTY: <u>Erie</u> TOWN/CITY: <u>Buffalo</u> VILLAGE: <u>.</u> 3. STREET LOCATION: <u>725</u> Crescent AVE			
	4. OWNERSHIP: a. public 🗆 b. private 🖾			
	5. PRESENT OWNER: Patricia McNamara A	DDRESS: 725 Crescent		
	6. USE: Original: <u>Residential</u> Pr	resent: <u>Residential</u>		
	7. ACCESSIBILITY TO PUBLIC: Exterior visible fro	m public road: Yes 🖾 No 🗀		
		Explain by permission		
	DESCRIPTION			
	8. BUILDING a. clapboard b. stone			
	MATERIAL: e. cobblestone \Box f. shingles \Box] g. stucco 🗌 other: <u>aluminum s</u> iding		
	9. STRUCTURAL a. wood frame with interlocking	ininte 🗖		
	9. STRUCTURAL a. wood frame with interlocking SYSTEM: b. wood frame with light memb			
	(if known) c. masonry load bearing walls d. metal (explain)			
	e. other			
	10. CONDITION: a. excellent D. good 🕱 c.	fair d deteriorated		
		if so,when?		
	c. list major alterations and dates (if)			

12. PHOTO: 7-21a





14.	THREATS TO BUILDING:	a. none known 🖾 b. zoning 🗆 c. roads 🗔 d. developers 🔲 e. deterioration 🗔 f. other:	
15.		AND PROPERTY: a. barn b. carriage house c. garage d. privy e. shed f, greenhouse g. shop h. gardens	
- 1	· · · · · · · · · · · · · · · · · · ·	i. landscape features: <u>small tree and shrubs in front</u> j. other:	yard
16.		BUILDING (check more than one if necessary): a. open land b. woodland c. scattered buildings d. d. densely built-up de. commercial d. f. industrial g. residential d. h. other:	

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

(Indicate if building or structure is in an historic district)

Building is situated on a standard sized lot within Olmsted's Parkside subdivision. House is located two blocks from Delaware Park, which was designed by Olmsted and is listed on the National Register, and north of the Zoo.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known): Two and a half story with Colonial Revival style details. Front facing gable roof. Glass and wood paneled door flanked on one side by single light rectangular window. First floor 1/1 window. Second floor semi-hexagonal bay. 1/1 squareheaded windows. Pedimented projecting gable. Palladian window <u>SIGNIFICANCE</u> in gable. Gabled two-story bay on west side. 19. DATE OF INITIAL CONSTRUCTION: <u>c. 1908</u>

ARCHITECT: _____

BUILDER:

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: Simplified form of Colonial Revival style with emphasis in gable of Palladian window. Crescent Avenue is the longest curvilinear street in the Parkside subdivision, stretching from Humboldt Avenue to Colvin Street. This street appears on Olmsted's early 1870's maps of "The Parkside." By the 1880's plans for Crescent Avenue had been modified by Olmsted to its current form. Portions of the street were deeded to the city by five different owners over a span of five years, beginning in 1887 near Humboldt and ending in 1892 near Colvin. Crescent Avenue begins and ends within the Parkside subdivision, following Olmsted's rule that a suburban neighborhood street "not lead with special directness toward the town."

Olmsted's Sketch Map of Buffalo, 1876 The Papers of Frederick Law Olmsted, Vol. III, by Charles E. Beveridge & David Schuyler, eds. (1983).

22. THEME:

Colonial Revival